

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110 INV No. AC2206567

INV Date 20/10/2022

Reference CS/EQI22009406/Uqy3e2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SMJ 9007R

Insured Veh. SGM 9174X

Claim No. DM22HO01643

Policy No.

Accident Date 21/09/2022

Inspection Date 26/09/2022

Description	Total
Survey Inspection	230.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	230.00
GST (7%)	16.10
Grand Total	246.10

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

		Affiliated to Federation Internation	nale Des Experts En Auto	omobile
	EQ INSURANCE C	OMPANY LTD	Ref:	CS/EQI22009406/Uqy3e2
	5 MAXWELL ROAD #17-00 TOWER BL MND COMPLEXSII	OCK	Date	e: 20/10/2022
			Cod	e: EQI
1.		Policy Particulars :	- THIRD PARTY CL	AIM
	Insured Veh.	SGM 9174X	Veh. Inspected	SMJ 9007R
	Policy No.		Coverage (\$)	0.00
	Claim No.	DM22HO01643	Excess (\$)	0.00
	Assign From	JOSEPHINE WONG	Assign Date	23/09/2022
2.		Vehicle Partic	ulars & Condition	
	Make & Model	MITSUBISHI ATTRAGE (A)	c.c	1193
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MMBSTA13AKH000678	Colour	WHITE
	Odometer	59875 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Condition	ons of Tyres	
		Size	Make	Balance
	R/H Front Tyre	185/55 R15	DUNLOP	6 mm
	L/H Front Tyre	185/55 R15	DUNLOP	6 mm
	R/H Rear Tyre	185/55 R15	DUNLOP	6 mm
	L/H Rear Tyre	185/55 R15	DUNLOP	6 mm
4.		Description	on of Damages	
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA	AR PORTION.	
	DAMAGES SEE DE	ETAILS.		
5.		General	Information	
	Accident Date	21/09/2022	Inspection Date	26/09/2022
	Survey held at	CYCLE & CARRIAGE.FULCO M	OTOR DEALER PL	
		NO.330 UBI ROAD 3 SINGAPORE 408650		
5a.			emarks	
		N WAS CONDUCTED ON A"WIT E TO YOUR INSTRUCTIONS, W		
5b.		Estimate I	Days of Repair	
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	5 W	orking Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 9007R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	C&C BADGE (SN)	NECESSARY	50.00	50.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	220.00
1	REVERSE CAMERA LENS (SN)	SHORTED / DAMAGED	380.00	380.00
1	REAR NUMBER PLATE WITH CASING (SN)	SCRATCHED	50.00	50.00
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	FACE, RR BUMPER (SN)	DENTED	900.00	900.00
10	CLIP, RR BUMPER (SN)	NECESSARY	40.00	40.00
1	BRACKET, RR BUMPER, LH (SN)	NECESSARY	24.00	24.00
1	BRACKET, RR BUMPER, RH (SN)	NECESSARY	24.00	24.00
1	BODY KIT, ATTRAGE (SN)	CRACKED	1,643.00	1,643.00
1	BUZZER, KEYLESS OPERATIO, RR (SN)	NOT NECESSARY	92.00	-
1	COVER, RR VENTILATOR (SN)	NOT NECESSARY	35.00	-
3	CLIP (SN)	NECESSARY	9.00	9.00
1	DUCT, RR VENTILATOR (SN)	NOT NECESSARY	31.00	-
1	MUD GUARD, RR LH (SN)	NOT NECESSARY	36.00	-
1	MUD GUARD, RR RH (SN)	NOT NECESSARY	36.00	-
1	TRIM, RR END (SN)	NOT NECESSARY	66.00	-
1	BOARD, TRUNK ROOM FLOOR (SN)	NOT NECESSARY	197.00	-
1	PANEL, RR END (SN)	TO REPAIR SEE LABOUR	431.00	-
1	WEATHERSTRIP, TRUNK LID (SN)	SERVICEABLE	158.00	-
1	PANEL, TRUNK LID (SN)	DENTED / BENT	803.00	803.00
1	HINGE, TRUNK LID, LH (SN)	NOT NECESSARY	205.00	-
1	HINGE, TRUNK LID, RH (SN)	NOT NECESSARY	205.00	-
1	LATCH, TRUNK LID (SN)	NOT NECESSARY	220.00	-
1	GARNISH, RR END PANEL CHROME (SN)	CRACKED	339.00	339.00
1	MARK, THREE-DIA (SN)	NECESSARY	61.00	61.00
1	MARK, ATTRAGE (SN)	NECESSARY	18.00	18.00
1	LAMP ASSY, COMB, RR RH (SN)	NOT NECESSARY	469.00	-

Report Ref No. CS/EQI22009406/Uqy3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	DECAL, MIVEC (SN)	NECESSARY	36.00	36.00
			6,888.00	4,617.00
	<u>LABOUR</u>			
	TO APPLY SEALANT KIT ON NEW PANEL.		240.00	80.00
	TO APPLY ANTI-CORROSION ON AFFECTED AREAS.		200.00	100.00
	TO REMOVE REAR REVERSE SENSOR FOR CHECK & TEST.		100.00	100.00
	TO REPLACE REAR BODY KIT.		800.00	320.00
	TO TRANSFER TRUNK LID COMPONENT & MECHANISM PARTS.		640.00	320.00
	TO REMOVE AND REINSTALL TRIMMING AND CARPETING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS.		640.00	320.00
	TO REPLACE TRUNK LID PANEL, REAR BUMPER, ETC -TO REPAIR RHR OTR QTR PANELTO CUT & REWELD REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF PANEL, RR END.		3,840.00	1,920.00
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS.		3,300.00	2,750.00
	TO CONDUCT DIAGNOSTIC CHECK ON USING MUT TESTER AND CLEAR TROUBLE CODE.		280.00	280.00
	CHECK WIRING & ELECTRICAL SYSTEM.		100.00	80.00
			10,140.00	6,270.00
	GRAND TOTAL		17,028.00	10,887.00

RECOMMENDED COST OF REPAIRS			10,887.00
-----------------------------	--	--	-----------

Report Ref No. CS/EQI22009406/Uqy3e2

CHUA KANG SENG

Licensed Appraiser



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process.
 This Form must be completed by the Policyholder and/or the Actual Driver
 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

4. The Issue and acceptance of this Profile for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/09/2022 15:13 (SGT) Reported by Date of Accident 21/09/2022 18:50 (SGT) Exact Location of Accident Devonshire Rd, Singapore DEVONSHIRE ROAD TO EXETER ROAD (NEAR 111 Additional Location Information SOMERSET)

Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMJ9007R

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner CHAN KENG HUA (ZENG QING HE) NRIC No SXXXX992E KEJOZ2017@GMAIL.COM **Email Address** Mobile Phone No

(Phone) +65-97567587 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Mitsubishi Model Attrage Variant

Exact purpose for which vehicle was being used at time of Private use

accident Are you claiming under your own insurance policy for repair to

No - Claiming third party your vehicle? Vehicle Category Private car

Transmission Auto 1193

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd. Policy Number / Cover Note Number 1900017451-02

DRIVER

Name of Driver GOH LECK WUN NRIC No SXXXX702I Date Of Birth 30/10/1981

Occupation Date Of Driving Pass Driving experience

Gender Mobile Number

Alt. Phone Number

Email Address Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance? Translator's name

Translator's ID Translator's phone number Translator's email

Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police? Police Station Name

Police Station Phone No Alt. Police Station Phone No. Police Station Address

Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Manufacturer Vehicle Model

SGM9174X Toyota

Accident report SC1X229M0005

Page 2 of 33

Yes

Indoor

Female

521125

Spouse

No

No

Dry

No

No

Yes

No

2

02/04/2002

20 YEARS AND 5 MONTHS

KEJOZ2017@GMAIL.COM

BLK 125 TAMPINES STREET 11 #04-498

(Phone) +65-91858001

Collision - Head to Rear

Traffic Police (Phone) +65-65470000

(Fax) +65-65474900

10 Ubi Avenue 3 Singapore 408865

No

 Vehicle Variant

 Vehicle Colour

 Vehicle Category
 Private car

 Name of Driver
 TAN YICK FUNG

 Contact Number
 (Phone) +65-98212636

 Address

 Address complement

 Postcode

 Insurance Company Name

 Nature Of Damage

 Details of property damaged in accident

 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Traffic Police Department for investigation.

- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Tirne

Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



ribe Circumstance of the Accident			/
	Marie C. Mar		
			/
			/
	/	/	
	for Vo.		
	2/10° 2/		
	X0 20.		
	64 100		
2	3 V		
	10 John 10 Joh		
/			
<u> </u>			
claration			
e declare the foregoing particulars are true	e in every respect.		v.
	1		

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)





Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

1 of 3 Report No. T/20220921/7062

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/09/2022 23:55			Vide Report No.:	Station Diary No.:		
Informan	t's Partic	ulars				
Name of Informant: GOH LECK WUN			Address: 125 TAMPINES STREET 11 #04-498 SINGAPORE 521125			
ID Type / ID No.: NRIC NO / S8173702I			Contact No.: Home/Office: Mobile: 91858001			
Nationality: SINGAPORE CITIZEN			Email: JOANNEGOHLW@GMAIL.COM			
Sex: Age: Date of Birth: Female 40 30/10/1981			Type of Informant: Driver			
Race: Chinese			Language: Institution / School Nam English			
Occupation:			Driving Licence Information: Class: 3	Date of Expiry:		

General Infor	mation of the Accide	ent			
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 21/09/2022 18:50	Type of Location: Y-Junction	
Location: DEVONSHIR Weather:	E ROAD	Road Surface:		Road Speed Limit:	
Clear		Dry			
Traffic Flow: Two Way		Traffic Control: Traffic Light - Wor	king	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance:	

Vehicle No.	Туре	Make	Model	Color	Conditio	No of
SGM9174X	Car	TOYOTA		Grey	Slightly Damaged	0
SMJ9007R	Car	MITSUBISHI	Attrage 1.2 CVT	White	Slightly Damaged	0



Details of Vehicle Insurance



Effective

2 of 3

10 Ubi Avenue 3 SINGAPORE 408865

Insurance Company

Tel No: 65470000

Traffic Police

Vehicle No.

Police Station Of Origin:

CONTINUATION OF REPORT

Insurance No

Report No. T/20220921/7062

Expiry Date

. 0111010 110.	1110	aranos company		moundin	00 110			-repris - care
SMJ9007R	AIC	G ASIA PACIFIC INSURA D.	190001	7451-02	2	25/03/2022	24/03/2023	
Details of Pe	erso	n Involved					Na San Layer	
Any Pedestri	an Ir	nvolved: No						
No. of Pedes	triar	ns Injured: NIL	l	Jse of Ped	destrian	Cross	sing: NA	
Driver						9-21/2	All Philip	and the
Name		TAN YICK FUNG		2	ID No.		S7902547Z	
Related Vehi	icle	SGM9174X (Car)			Conta	ct No.	98212636	
Hospital/Clin	ic	NIL			Class of Driving Licence & Expiry		Class: NIL Date of Expiry: NIL	
Date		NIL		Date		NIL		
No. of Days	gran	ted Medical Leave	VIL I	Degree of		NIL		
Driver							A Section	
Name		GOH LECK WUN			ID No		S8173702I	
Related Vehi	icle	SMJ9007R (Car)			Contact No.		91858001	
Hospital/Clin	ic	NIL		Class Drivin Licent Expiry	g ce &	Class: 3 Date of Exp	iry: NIL	
Date		NIL		Date		NIL		
No. of Days	gran	ted Medical Leave	VIL I	Degree of		NIL		

Brief Details.

I was turning from Devonshire Road to Exeter Road near 111 Somerset. When I was approaching the Y junction, I stopped my vehicle to observe the incoming traffic. A few seconds later, a vehicle hit or collided against my vehicle from behind. We concluded to send my vehicle to workshop for repair. The quotation/invoice will be sent to the involved vehicle's driver (Mr Tan Yick Fung, S7902547Z, Vehicle No: SGM9174X) to make the payment. He will let me know whether he will want to settle outside (paid direct to the workshop) or claim from his insurance. We have exchanged contact numbers, NRIC and name, also took photos of the damaged vehicles.





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 3 Report No. T/20220921/7062

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 21/09/2022 23:55
Officer In Charge Of Case: TP / TPIB / ANG YI TING, STEPHANIE Contact No.: 65476414	Classification Of Case:

NP168



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMJ 9007R

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMJ 9007R

RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMJ 9007R

RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315





