

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/EQ/22009406/Ug43

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond. Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 19/10/2012

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$

TP

10887

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

19/10/12 repair - rear bumper O/S addition 1/2 day loss + 320
 PIP & 10887.00 informed Marcus. (Red 6141, 36%)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 67461000 Fax: (65) 64875857

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CHAN KENG HUA (ZENG QINGHE)	Cust No/Name /CHAN KENG HUA (ZENG QINGHE)
125 Tampines Street 11	Reg No/Reg Date SMJ9007R / 25/03/2019
#04-498	Date In/Mileage 22/09/2022/ 59724
Singapore 521125	Chassis No MMBSTA13AKH000678
Contact No Mobile: 97567587	Engine No 3A92UHM3363
	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
CTP00040	Cash	23/09/2022/ 11:10	LER	972 / Mars Ler	11641	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
Z TEXT						
ACCIDENT ON 21/09/2022 ALONG DEVONSHIRE RD						
OWNER CLAIMING THIRD PARTY						
REQUIRED REPLACEMENT CAR						
TP# SGM9174X TP INS: EQ						
M SUNDRY						
TO APPLY SEALANT KIT ON NEW PANEL						
M SUNDRY						
TO APPLY ANTI-CORROSION ON AFFECTED AREAS						
M SUNDRY						
C & C BADGE						
M SUNDRY						
TO SUPPLY REVERSE SENSOR SET						
M SUNDRY						
TO SUPPLY REVERSE CAMERA LENS						
E PNT88000						
TO REMOVE REAR REVERSE SENSER FOR CHECK & TEST						
E PNT88000						
TO REPLACE REAR BODY KIT						
E PNT88000						
TO TRANSFER TRUNK LID COMPONENT & MECHANISM PARTS						
E PNT88000						
TO REMOVE AND REINSTALL TRIMMING AND CAPERTING TO GIVE WAY ACCESS						
REPAIR ON REAR ACCIDENT AFFECTED AREAS						
E PNT88000						
TO REPLACE TRUNK LID PANEL, REAR BUMPER,ETC						
-TO REPAIR RHR OTR QTR PANEL						
-TO CUT & REWELD REAR END PANEL						
STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS						
E PNT88000						
REAR NUMBER PLATE WITH CASING						
E PNT98000						
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS						

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate

80	.	240.00
100	.	200.00
ner	✓	50.00
shored	220	280.00
shored/page	✓	380.00
320	.	800.00
320	.	640.00
320	.	640.00
1920	.	3840.00
640		
scr	✓	50.00
2750		3300.00
530		

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

CYCLE & CARRIAGE

330 Ubi Road 3, Singapore 408650 Tel: (65) 67461000 Fax: (65) 64875857

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CHAN KENG HUA (ZENG QINGHE)	Cust No/Name /CHAN KENG HUA (ZENG QINGHE)
125 Tampines Street 11	Reg No/Reg Date SMJ9007R / 25/03/2019
#04-498	Date In/Mileage 22/09/2022/ 59724
Singapore 521125	Chassis No MMBSTA13AKH000678
Contact No Mobile: 97567587	Engine No 3A92UHM3363
	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	23/09/2022/ 11:10	LER	972 / Mars Ler	11641			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								50.00
SUNDRIES								280.00
A 10028901								100.00
TO CONDUCT DIAGNOSTIC CHECK ON USING MUT TESTER AND CLEAR TROUBLE CODE								
A 54900099								
CHECK WIRING & ELECTRICAL SYSTEM								
M FACE,RR BUMPER					1.00	900.00	00.00	900.00
M CLIP,RR BUMPER					10.00	4.00	00.00	40.00
M BRACKET,RR BUMPER,LH					1.00	24.00	00.00	24.00
M BRACKET,RR BUMPER,RH					1.00	24.00	00.00	24.00
M BODY KIT, ATTRAGE					1.00	1643.00	00.00	1643.00
M BUZZER,KEYLESS OPERATIO,RR					1.00	92.00	00.00	92.00
M COVER,RR VENTILATOR					1.00	35.00	00.00	35.00
M CLIP,GEARSHIFT CONTROL LIN					3.00	3.00	00.00	9.00
M DUCT,RR VENTILATOR					1.00	31.00	00.00	31.00
M MUD GUARD,RR LH					1.00	36.00	00.00	36.00
M MUD GUARD,RR RH					1.00	36.00	00.00	36.00
M TRIM,RR END					1.00	66.00	00.00	66.00
M BOARD,TRUNK ROOM FLOOR					1.00	197.00	00.00	197.00
M PANEL,RR END					1.00	431.00	00.00	431.00
M WEATHERSTRIP,TRUNK LID					1.00	158.00	00.00	158.00
M PANEL,TRUNK LID					1.00	803.00	00.00	803.00
M HINGE,TRUNK LID,LH					1.00	205.00	00.00	205.00
M HINGE,TRUNK LID,RH					1.00	205.00	00.00	205.00
M LATCH,TRUNK LID					1.00	220.00	00.00	220.00
M GARNISH,RR END PANEL					1.00	339.00	00.00	339.00
M MARK,THREE-DIA					1.00	61.00	00.00	61.00
M MARK,ATTRAGE					1.00	18.00	00.00	18.00
M LAMP ASSY,COMB,RR RH					1.00	469.00	00.00	469.00
M DECAL,MIVEC					1.00	36.00	00.00	36.00
SURVEYOR NAME: Mars Ler								
SURVEYOR SIGNATURE: [Signature]								
DATE: 26/09/22 @ 10am								
REMARKS: Take photo before party.								

Confirm & accepted by

P/P # 10887

Nett 17,028.00
7% GST on 17028.00 1191.96

Total Payable 18,219.96

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 67461000 Fax: (65) 64875857

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CHAN KENG HUA (ZENG QINGHE)	Cust No/Name /CHAN KENG HUA (ZENG QINGHE)
125 Tampines Street 11	Reg No/Reg Date SMJ9007R / 25/03/201
#04-498	Date In/Mileage 03/10/2022/ 60141
Singapore 521125	Chassis No MMBSTA13AKH000678
Contact No Mobile: 97567587	Engine No 3A92UHM3363
07/10/	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	14/10/2022/ 08:38	LER	972 / Mars Ler	11641			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z TEXT								
ACCIDENT ON 21/09/2022 ALONG DEVONSHIRE RD								
OWNER CLAIMING THIRD PARTY								
REQUIRED REPLACEMENT CAR (CHAN'S)								
TP# SGM9174X TP INS: EQ INSURANCE								
M SUNDRY								80.00
TO APPLY SEALANT KIT ON NEW PANEL								
M SUNDRY								100.00
TO APPLY ANTI-CORROSION ON AFFECTED AREAS								
M SUNDRY								50.00
C & C BADGE								
M SUNDRY								220.00
TO SUPPLY REVERSE SENSOR SET								
E PNT88000								100.00
TO REMOVE REAR REVERSE SENSER FOR CHECK & TEST								
E PNT88000								320.00
TO REPLACE REAR BODY KIT								
E PNT88000								320.00
TO TRANSFER TRUNK LID COMPONENT & MECHANISM PARTS								
E PNT88000								320.00
TO REMOVE AND REINSTALL TRIMMING AND CAPERTING TO GIVE WAY ACCESS								
REPAIR ON REAR ACCIDENT AFFECTED AREAS								
E PNT88000								1920.00
TO REPLACE TRUNK LID PANEL, REAR BUMPER,ETC								
-TO REPAIR REAR END PANEL								
-TO REPAIR RHR OTR QTR PANEL								
STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS								
E PNT88000								50.00
REAR NUMBER PLATE WITH CASING								
E PNT98000								2750.00
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS								
M SUNDRY								20.00
SUNDRIES								

Confirm & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 67461000 Fax: (65) 64875857



mitsubishi
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CHAN KENG HUA (ZENG QINGHE)	Cust No/Name / CHAN KENG HUA (ZENG QINGHE)
125 Tampines Street 11	Reg No/Reg Date SMJ9007R / 25/03/201
#04-498	Date In/Mileage 03/10/2022/ 60141
Singapore 521125	Chassis No MMBSTA13AKH000678
Contact No Mobile: 97567587	Engine No 3A92UHM3363
07/10/	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	14/10/2022/ 08:38	LER	972 / Mars Ler	11641			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
A 10028901								280.00
TO CONDUCT DIAGNOSTIC CHECK ON USING MUT TESTER AND CLEAR TROUBLE CODE								
A 54900099								80.00
CHECK WIRING & ELECTRICAL SYSTEM								
M SUNDRY								380.00
TO SUPPLY REVERSE CAMERA LENS								
X	FACE,RR BUMPER			1.00	900.00	00.00	900.00	
X	CLIP,RR BUMPER			10.00	4.00	00.00	40.00	
X	BRACKET,RR BUMPER,LH			1.00	24.00	00.00	24.00	
X	BRACKET,RR BUMPER,RH			1.00	24.00	00.00	24.00	
M	BODY KIT, ATTRAGE			1.00	1643.00	00.00	1643.00	
X	CLIP,GEARSHIFT CONTROL LIN			3.00	3.00	00.00	9.00	
X	PANEL,TRUNK LID			1.00	803.00	00.00	803.00	
X	GARNISH,RR END PANEL			1.00	339.00	00.00	339.00	
X	MARK,THREE-DIA			1.00	61.00	00.00	61.00	
X	MARK,ATTRAGE			1.00	18.00	00.00	18.00	
X	DECAL,MIVEC			1.00	36.00	00.00	36.00	

Confirm & accepted by

	Nett	10,887.00
7% GST on	10887.00	762.09

Total Payable	11,649.09
---------------	-----------

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	22/09/2022 15:13 (SGT)
Reported by	Both
Date of Accident	21/09/2022 18:50 (SGT)
Exact Location of Accident	Devonshire Rd, Singapore
Additional Location Information	DEVONSHIRE ROAD TO EXETER ROAD (NEAR 111 SOMERSET)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ9007R
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHAN KENG HUA (ZENG QING HE)
NRIC No	SXXXX992E
Email Address	KEJOZ2017@GMAIL.COM
Mobile Phone No	(Phone) +65-97567587
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Attrage
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1193

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	1900017451-02

DRIVER

Name of Driver	GOH LECK WUN
NRIC No	SXXXX702I
Date Of Birth	30/10/1981

Occupation	Indoor
Date Of Driving Pass	02/04/2002
Driving experience	20 YEARS AND 5 MONTHS
Gender	Female
Mobile Number	(Phone) +65-91858001
Alt. Phone Number	-
Email Address	KEJOZ2017@GMAIL.COM
Address	BLK 125 TAMPINES STREET 11 #04-498
Address complement	-
Postcode	521125
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGM9174X
Vehicle Manufacturer	Toyota
Vehicle Model	-

Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	TAN YICK FUNG
Contact Number	(Phone) +65-98212636
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

A - SMJ 9007 R

B - SGM 9174 X

Describe Circumstance of the Accident


Refer to Police Report
No. T/20220921/7062.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)



Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/09/2022 23:55	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: GOH LECK WUN			Address: 125 TAMPINES STREET 11 #04-498 SINGAPORE 521125		
ID Type / ID No.: NRIC NO / S8173702I			Contact No.: Home/Office: Mobile: 91858001		
Nationality: SINGAPORE CITIZEN			Email: JOANNEGOHLW@GMAIL.COM		
Sex: Female	Age: 40	Date of Birth: 30/10/1981	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation:			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

General Information of the Accident				
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 21/09/2022 18:50	Type of Location: Y-Junction
Location: DEVONSHIRE ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Conditio	No of
SGM9174X	Car	TOYOTA		Grey	Slightly Damaged	0
SMJ9007R	Car	MITSUBISHI	Attrage 1.2 CVT	White	Slightly Damaged	0



Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMJ9007R	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1900017451-02	25/03/2022	24/03/2023

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	TAN YICK FUNG		ID No.	S7902547Z
Related Vehicle	SGM9174X (Car)		Contact No.	98212636
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave		NIL	Degree of	NIL
Driver				
Name	GOH LECK WUN		ID No.	S8173702I
Related Vehicle	SMJ9007R (Car)		Contact No.	91858001
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave		NIL	Degree of	NIL

Brief Details.

I was turning from Devonshire Road to Exeter Road near 111 Somerset. When I was approaching the Y junction, I stopped my vehicle to observe the incoming traffic. A few seconds later, a vehicle hit or collided against my vehicle from behind. We concluded to send my vehicle to workshop for repair. The quotation/invoice will be sent to the involved vehicle's driver (Mr Tan Yick Fung, S7902547Z, Vehicle No: SGM9174X) to make the payment. He will let me know whether he will want to settle outside (paid direct to the workshop) or claim from his insurance. We have exchanged contact numbers, NRIC and name, also took photos of the damaged vehicles.



**SINGAPORE
POLICE FORCE**



T/20220921/7062

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20220921/7062

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
ANG YI TING, STEPHANIE
Contact No.: 65476414

Signature Of Informant:
The identity of the person making this report has
been authenticated by Singpass. No signature is
required.

Date/Time:
21/09/2022 23:55

Classification Of Case:



CERTIFICATE OF INSURANCE

CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : CHAN KENG HUA (ZENG QINGHE)
Period of Insurance : 25 Mar 2022 To 24 Mar 2023
Engine No. : 3A92UHM3363
Chassis No. : MMBSTA13AKH000678

Vehicle No. : SMJ9007R
Policy No. : 1900017451-02
Endorsement No. :
Issued Date : 18 Feb 2022

ABOUT THE COVER

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT

Engine Capacity/Tonnage : 1,193.00 CC

Sum Insured : Market Value

First Year of Registration : 2019

Driver Restriction : NA

Off Peak Car : No

Insuring with COE/PAFF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of S\$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Mileage Condition : Unlimited Mileage

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Chan Keng Hua (Zeng Qinghe) - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708688

4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504620222

C&CMICP2 - KELVIN

239 ALEXANDRA ROAD
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

SSCZSS