

ASS. REQ. BY:

REF:

LIP: 220094291K6

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMS 9034 P Yr Regn: 03, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Mit Attrage c.c. 1193

Colour

M.L. Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

74062

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MMBSTA13AKH 003352

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

185/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Fairken

Front

R/Bal.

mm

L/Bal.

mm

D.O.A.

21/9/22

Rear

R/Bal.

mm

L/Bal.

mm

D.O.I.

26/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

C/S/Rm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

S - RS - SI

Fixing

Others

110

50

50

26

80

TOTAL

316

Report Format :

Lump Sum / I.B.I: (\$

160 SIN MING DRIVE #172
TONG LUCK AUTO

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: TP-WD 6097T
 Repairer Reference: 73029
 Date calculated: 23/09/2022 8:32 AM

Full Report
Registration: SMS 9034P
Printed: 23/09/2022 8:32 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	Liberty Insurance Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-WD 6097T	Date of Incident:	21/09/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: MITSUBISHI
 Model: ATTRAGE (A13A)
 Sub Model: BASE MODEL
 Model Sheet Number: 32 AT 01
 Registration: SMS 9034P
 VIN number:
 Odometer: 74061

Model Specs

AIR CONDITIONING	FOG LAMPS	1.2 LTR 59KW	CVT AUTOMATIC
TYRES 185/55 HR 15	FRONT SPOILER	TWO COAT METALLIC	PREPARE OFF VEHICLE

*Not Authorised
 Penny B & pay
 4 days*

Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
NO NUMBER	PREPARATION TIME		2.0	10.00
514110 00)	RENEW FRONT BUMPER		7.0	35.00
	INCLUDES: R + R NECESSARY ATTACHED PARTS			
514121 10)	R + R FRONT BUMPER ATTACHED PARTS		5.0	25.00
541010 00)	R + R RIGHT HEADLAMP		4.0	20.00
NO NUMBER	ADJUST HEADLAMPS		2.0	10.00
422025 00	R + R RIGHT FRONT WHEEL ARCH COVER		5.0	25.00
NO NUMBER	R + R FRONT UPPER PANEL		5.0	25.00
0340	FRT BUMPER SUPPORT REPAIR		15.0*	75.00
0742	R/F WING REPAIR		10.0*	50.00
1001	LWR RADIATOR SUPPORT REPAIR		10.0*	50.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		6.50	65.0	325.00
Total of Labour				325.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 3
 Acknowledged by Repairer
 Signature:
 Date:

Audatex System Using Manufacturer Times

PRINT DATE 23/09/2022

Paint

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
	UPPER FRONT PANEL SURFACE PAINT	4.0	
	FRONT BUMPER NEW PART PAINT K1R	14.0	
	FRT BUMPER TRIM CAP NEW PART PAINT K1R	3.0	
	R/F WING REPAIR PAINTING <50%	11.0	
	FRT BUMPER SUPPORT SURFACE PAINT	6.0	
	LWR RADIATOR SUPPORT SURFACE PAINT	4.0	

Paint Material Per Part

Code	Description	Price SGD
1017	UPPER FRONT PANEL SURFACE PAINT	3.49
0283	FRONT BUMPER NEW PART PAINT K1R	69.86
0349	FRT BUMPER TRIM CAP NEW PART PAINT K1R	0.49
0742	R/F WING REPAIR PAINTING <50%	12.27
0340	FRT BUMPER SUPPORT SURFACE PAINT	9.96
1001	LWR RADIATOR SUPPORT SURFACE PAINT	4.48

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			
Time Paint		42.0	
Preparation Main Work Metal	2.50	25.0	125.00
Preparation Comp. Work Plastic	0.50	5.0	25.00
Total	10 WU/h	72.0	360.00

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	70.35
Repair Painting	12.27
Surface-/Blend Paint	17.93
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	138.15

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01	Price SGD
0283	FRONT BUMPER	6400F244	Original	By ✓	280.00
0391	FRONT SPOILER	MZ330660	Original	By ✓	380.00
0349	FRT BUMPER TRIM CAP	6400F205BA	Original	By ✓	12.00
0415	GRILLE	6402A301	Original	CMT ✓	220.00
0843	L/FASTENING CLIP	MU001623	Original	By ✓	15.00
0411	LWR RADIATOR GRILLE	6402A268	Original	By ✓	75.00
0844	R/FASTENING CLIP	MU001623	Original	By ✓	25.00
0652	R/F BUMPER COVER	6402A330	Original	By ✓	55.00
0648	R/F FOG LAMP	8321A545	Original	By ✓	195.00
0562	R/F HEADLAMP	8301C544	Original	By ✓	205.00
0318	R/F UPP BUMPER BRKT	6400F222	Original	By ✓	10.00

Code	Description	Part Number	Part Source	Price SGD
0842	R/F WHEELHOUSE COVER	5370B890	Original	TA ✓ 52.00
1017	UPPER FRONT PANEL	5256B985	Original	CM ✓ 48.00
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings			0.00
	Subtotal			1,572.00
	Addition(+10.00%)			157.20
	Total			1,729.20

Extras

Code	Description	Price SGD
1000	FRONT NUMBER PLATE	✓ 35.00*
1001	TOWING FEE	✓ 50.00*
	Total Extras	85.00

Final Calculation

	SGD	SGD
Parts		
Addition(+10.00%)	1,572.00	
Total Parts	157.20	1,729.20
Labour Time Base 10 WU/h		
Total 65.0 WU X 50.00 SGD/h	325.00	
Total of Labour		325.00
Total Of Extras		85.00
Paint Work Time Base 10 WU/h		
Labour Cost 72.0 WU X 50.00 SGD/h	360.00	
Material Cost	138.15	
Total Paint Including Material		498.15
Repair Cost Excludes GST		2,637.35
GST (+7.0%)		184.61
Repair Cost Included GST		2,821.96

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	22/09/2022 17:03 (SGT)
Reported by	Both
Date of Accident	21/09/2022 15:55 (SGT)
Exact Location of Accident	15 Gul Ave, Singapore 629658
Additional Location Information	at Tat Eng Industries Pte Ltd
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMS9034P
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Tay Jun Ming Rayner
NRIC No	SXXXX280J
Email Address	jmray@live.com.sg
Mobile Phone No	(Phone) +65-96657952
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Attrage
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1200

INSURANCE COMPANY

Name of Insurance Company	Etiga Insurance Pte Ltd
Policy Number / Cover Note Number	MA018376

DRIVER

Name of Driver	Tay Jun Ming Rayner
NRIC No	SXXXX280J
Date Of Birth	16/06/1988
Occupation	Indoor

IMPORTANT NOTICE

1. Please fill in correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the policyholder and/or the Actual Driver.
3. Information provided must be as true and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the CICA Insurance Management Centre established by the General Insurance Association of Singapore (GIA) for use and use that insurers of this report will for a time be made available upon application by interested parties.
7. By the forwarding of this report to the insurers, you hereby consent to the archiving of this report at the police and to copies of the report being made available to insurers.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data and information set out in this form (and any other personal information provided by me or possessed by my insurer collectively the "Personal Information") and to store and transfer such Personal Information to all insurer(s) who have insured vehicles, or vehicles in this accident (all insurers) and have insured vehicles involved in this accident shall be collectively referred to as the "Insurers"; the Insurers, lawyers, law firms, the Maritime Authority of Singapore and any relevant government authority (such as the police) for the purpose(s) of

(i) processing, handling and/or dealing with my claims and/or the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to third parties about delivery of the same as well as on the external cover of envelopes and packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, for one or more of the "Purposes";

(b) All insurer(s) who have insured vehicles involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms, which may be based outside of Singapore) for one or more of the above Purposes.

Signature 22/09/22 8:55am

Polytechnic Signature, Date & Time

Actual Driver's Signature (if driver) and the Insurer's Signature, Date & Time

Signature Lim Lai Fong
Witnessed by Reporting Centre Personnel
(Name and NRIC Number)

Sketch Plan

