

ASS. REC. BY:

REF:

CS/SMR 22009461/Day³

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or NoLum Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 8HIA 4864Y Yr Regn: June / 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Ioniq C.C. 1580Colour: Blue L/C: Insured / Std / NI / NASp. Reading: 370587 T/Radio: Insured / Std / NI / NAEng/No: G4LEKUA295299C/No: KMHLC851CVKU164349

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65715R: -11-

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 26/09/2022 D.O.I. 27/09/2022Survey held at 3.7 Post sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

4/5 Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SMR 8HIA 4812L14/02/2024 from 2/5 9,800/- with 8 days of rep (Red. \$18,501.15, 65%)

Date/Time, File Pass to?

☐ : Preli. Report☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format: TPLump Sum / I.B.I.: (\$ 9800/-)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHA4864Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Sep 2022
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G4LEKU295299
Chassis No.:	KMHC851CVKU164349
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,373.00
Original Registration Date:	26 Jun 2019
First Registration Date:	26 Jun 2019
Transfer Count:	0
Actual ARF Paid:	\$12,523.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jun 2027
PARF Rebate Amount:	\$9,392.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$23,872.00
COE Rebate Amount:	\$14,132.00
Total Rebate Amount:	\$23,524.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Sep 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	26/09/2022 17:21 (SGT)
Reported by	Driver
Date of Accident	26/09/2022 10:15 (SGT)
Exact Location of Accident	15 Beach Rd, Singapore 190015
Additional Location Information	OSCP
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA4864Y
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-91000851
Alternative Phone No	(Office) +65-87256880

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1580

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Policy Number / Cover Note Number	VFX/P2419138

DRIVER

Name of Driver	NG LYE NGUAN (HUANG LAIYUAN)
NRIC No	SXXXX204G
Date Of Birth	02/05/1975
Occupation	Outdoor

Date Of Driving Pass	23/09/2009
Driving experience	13 YEARS
Gender	Male
Mobile Number	(Phone) +65-91000851
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 18 JALAN SULTAN #02-156
Address complement	-
Postcode	190018
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 26.09.2022 AT ABOUT 1015HRS I WAS DRIVING MY SHA4864Y HOME AT BLOCK 15 BEACH ROAD . AS I ENTERED THE OSCP , VEHICLE B SHC4812L DROVE OUT FROM A PARALLEL PARKING ON MY LEFT. HIS VEHICLE B RIGHT FTOHT SIDE SWIPE MY VEHICLE A LEFT FRONT. AFTER IMPACT I HURT MY SHOULDER AND LEFT SIDE WAIST AREA. PARTICULARS EXCHANGED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC4812L
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	MARZUKI BIN MOHD
NRIC No	SXXXX210J
Contact Number	(Phone) +65-96376402
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	RIGHT FRONT
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	NG LYE NGUAN (HUANG LAIYUAN)
Gender	Male
Phone No	(Phone) +65-91000851
Address	BLK 18 JALAN SULTAN #02-156
Address Complement	-
Post Code	190018
Approximate Age Years Old	47
Injuries Sustained	SHOULDER AND LEFT SIDE WAIST
Injured person in which vehicle?	SHA4864Y
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A - SHA 4864Y

B - SHC 4812L

BLK 15 BEACH ROAD

OSCP

T

T

T

T

Describe Circumstances of the Accident

ON 26.09.2022 AT ABOUT 1015HRS I WAS DRIVING MY SHA4864Y HOME AT BLOCK 15 BEACH ROAD . AS I ENTERED THE OSCP , VEHICLE B SHC4812L DROVE OUT FROM A PARALLEL PARKING ON MY LEFT. HIS VEHICLE B RIGHT FTOHT SIDE SWIPE MY VEHICLE A LEFT FRONT.
AFTER IMPACT I HURT MY SHOULDER AND LEFT SIDE WAIST AREA.
PARTICULARS EXCHANGED

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

26-09-2022 1450HRS



Witnessed by Reporting Centre Personnel

Signature

Customer:	LIM TAN		Date:	9/27/2022 9:40 AM		
Company:	01-42		VIN			
License NO:	SHA 4864Y		Technician:			
Odometer:			Order NO:			
VEHICLE ALIGNMENT REPORT HYUNDAI, IONIC AE Series EV, 17-17 (Customized)						
Primary Angles			Initial	Specifications Min. Max.		Final
Front	Caster	Left	5°10'	4°00'	5°00'	5°06'
		Right	5°04'	4°00'	5°00'	5°00'
	Camber	Left	-1°36'	-1°00'	0°00'	-2°00'
		Right	-0°24'	-1°00'	0°00'	-0°18'
	Toe	Left	0°03'	-0°03'	0°09'	0°57'
		Right	-0°06'	-0°03'	0°09'	-0°54'
Total		-0°03'	-0°06'	0°18'	0°03'	
Rear	Camber	Left	-1°12'	-1°42'	-0°42'	-1°06'
		Right	-1°00'	-1°42'	-0°42'	-1°06'
	Toe	Left	0°15'	0°00'	0°18'	0°15'
		Right	0°00'	0°00'	0°18'	0°00'
		Total	0°15'	0°00'	0°36'	0°15'
	Thrust Angle		0°08'	----		0°08'
Secondary Angles			Initial	Specifications Min. Max.		Final
SAI	Left	14°01'	13°30'	14°30'	14°01'	
	Right	13°55'	13°30'	14°30'	13°55'	
Included Angle	Left	12°25'	----	----	12°01'	
	Right	13°31'	----	----	13°37'	
Toe Out On Turns	Left	----	----	----	----	
	Right	----	----	----	----	
Max Turn Inside	Left	----	----	----	----	
	Right	----	----	----	----	
Toe Curve Change	Left	----	----	----	----	
	Right	----	----	----	----	
Setback	Front	7mm	----	----	7mm	
	Rear	3mm	----	----	3mm	
Track Width Diff.		-1mm			-1mm	
Wheel Base Diff.		4mm			4mm	
Front Ride Height	Left	----	----	----	----	
	Right	----	----	----	----	
Rear Ride Height	Left	----	----	----	----	
	Right	----	----	----	----	
Frame Angle					----	

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 26-Sep-22

INSURANCE: SMRT

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 4864 Y

Description	Qty	List Price	Amount
Bonnet <i>HH</i>	1	\$ 2,253.80	\$ 2,253.80
Bonnet Hinge (LH/RH) <i>HH</i>	2	\$ 118.70	\$ 237.40
Bonnet Moulding <i>HH</i>	1	\$ 41.40	\$ 41.40
Bonnet Insulator <i>HH</i>	1	\$ 230.10	\$ 230.10
Bonnet Insulator Clips <i>HH</i>	1	\$ 15.00	\$ 15.00
Front Bumper Cover <i>cut / Damaged / mounting broken</i>	1	\$ 481.10	\$ 481.10
Front bumper top cover <i>HH</i>	1	\$ 476.30	\$ 476.30
Front Bumper Reinforcement ABSORBER (LH) <i>HH</i>	1	\$ 186.50	\$ 186.50
Front Bumper Moulding Centre Upper <i>HH</i>	1	\$ 368.50	\$ 368.50
Front Bumper Moulding <i>HH</i>	1	\$ 93.60	\$ 93.60
Front Bumper Bracket Top (LH) <i>2pc</i>	1	\$ 35.00	\$ 35.00
Front Bumper Bracket (LH) <i>HH</i>	1	\$ 28.00	\$ 28.00
Front Bumper Retainer Mounting (LH) <i>HH</i>	1	\$ 65.30	\$ 65.30
Front Bumper Clips 10 pcs <i>HH</i>	1	\$ 25.00	\$ 25.00
Front Bumper Grille (LH) <i>HH</i>	1	\$ 186.90	\$ 186.90
Front bumper air duct (LH) <i>HH</i>	1	\$ 153.80	\$ 153.80
Day Light ,LH <i>HH</i>	1	\$ 642.50	\$ 642.50
BUZZER ASSY - PIEZO (LH) <i>HH</i>	1	\$ 388.00	\$ 388.00
Headlamp Support Panel Assy <i>broken</i>	1	\$ 1,139.30	\$ 1,139.30
Headlamp(LH) <i>mounting broken</i>	1	\$ 3,987.30	\$ 3,987.30
Frt Pillar Upper Cover - outer (LH) <i>distorted</i>	1	\$ 89.60	\$ 89.60
Front Fender(LH) <i>Recess</i>	1	\$ 490.70	\$ 490.70
Front Fender Apron Panel side support (LH) <i>HH</i>	1	\$ 238.80	\$ 238.80
Front Fender Apron Panel (LH) <i>HH</i>	1	\$ 756.20	\$ 756.20
Front Fender Apron Panel Upper(LH) <i>HH</i>	1	\$ 329.00	\$ 329.00
Front Fender Shield (LH) <i>HH</i>	1	\$ 164.70	\$ 164.70
Frt Door(LH) <i>Recess</i>	1	\$ 1,797.20	\$ 1,797.20
Frt Door Rubber <i>sn</i>	1	\$ 250.00	\$ 250.00
Front Door Regulator (LH) <i>HH</i>	1	\$ 750.40	\$ 750.40
Front Door Power Motor, LH <i>HH</i>	1	\$ 689.20	\$ 689.20
Front Door Hinge Upper (LH) <i>HH</i>	1	\$ 165.76	\$ 165.76
Front Door Hinge Lower (LH) <i>HH</i>	1	\$ 153.70	\$ 153.70
Front Door Check (LH) <i>HH</i>	1	\$ 72.98	\$ 72.98
Front Door Mirror ASSY (LH) <i>HH</i>	1	\$ 1,691.70	\$ 1,691.70
Front Door Protector(LH) <i>HH</i>	1	\$ 186.20	\$ 186.20
Front Door Outer Moulding (LH) <i>HH</i>	1	\$ 110.10	\$ 110.10
Rocker Panel Outer Garnish <i>mounting broken</i>	1	\$ 715.60	\$ 715.60
Front Wheel Rim (LH) <i>distorted</i>	1	\$ 1,124.20	\$ 1,124.20
Front Wheel Hub assy (LH) <i>Recess</i>	1	\$ 678.50	\$ 678.50
Front Wheel Hub Cap <i>cut</i>	1	\$ 346.40	\$ 346.40
Front Shock Absorber(Assy)(LH) <i>distorted</i>	1	\$ 372.50	\$ 372.50
Front Shock Absorber Mounting (LH) <i>HH</i>	1	\$ 372.50	\$ 372.50
Front Drive Shaft (LH) <i>HH</i>	1	\$ 1,136.70	\$ 1,136.70

2110:30

Rack & Pinion Assy <i>HH</i>	1	\$ 2,387.40	\$ 2,387.40
STG Tie Rod <i>HH</i>	1	\$ 125.60	\$ 125.60
STG Tie End <i>HH</i>	1	\$ 94.70	\$ 94.70
Stabilizer Bar <i>HH</i>	1	\$ 326.80	\$ 326.80
Stabilizer Bar Link <i>HH</i>	1	\$ 92.10	\$ 92.10
Front Suspension Lower Arm (LH) <i>distal</i>	1	\$ 596.80	\$ 596.80
Knuckle Arm (LH) <i>distal</i>	1	\$ 663.60	\$ 663.60
SUB TOTAL			\$ 28,004.44
LESS 20%			\$ 5,600.89
DISCOUNTED TOTAL			\$ 22,403.55
Front Fender Advertisement Logo (LH) <i>HH</i>	SN 1	\$ 100.00	\$ 100.00
Emblem-Blue Drive (LH) <i>HH</i>	SN 1	\$ 26.60	\$ 26.60
Front Door Comfort Logo (LH) <i>HH</i>	SN 1	\$ 75.00	\$ 75.00
Front Door Advertisement Logo (LH) <i>HH</i>	SN 1	\$ 100.00	\$ 100.00
Front Tyre(LH) <i>SN</i>	SN 1	\$ 216.00	\$ 216.00
SUB TOTAL			\$ 517.60
Labour Charge			
Panel Beating	1	\$1,800.00	\$1,800.00
Spray Painting Charge	1	\$1,600.00	\$1,600.00
Wiring Charge	1	\$100.00	\$100.00
Tuff Kote	1	\$100.00	\$100.00
Towing Charge	1	\$80.00	\$80.00
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00
Re-set Frt Power Window System	1	\$200.00	\$200.00
Four Wheel Alignment	1	\$120.00	\$120.00
Remove/Refix Undercarriage (Frt)	1	\$400.00	\$400.00
Remove/Refix Radiator	1	\$90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00
Remove/Refix Steering Rack/Wheel/Dr Shaft	1	\$150.00	\$150.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
TOTAL LABOUR			\$5,400.00
ESTIMATE TOTAL			\$28,321.15

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_ltr@bifrostauto.com

27/09/2022 @ 1300h

NA AWH

2/Week 8 days.

Rym

LKK Auto

10,971.64
1/3 9,800/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

11008-30
8,906.64

✓ List
✓
X
275.00

700/-
700/-
30/-
40/-
44
60/-
44
60/-
150/-
44
44
150/-

1890.00