

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22009471/Aqy3q2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	: 29/11/2022	
			Code	e: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJL 4670H	Veh. Inspected	SJT 2457D	
	Policy No.	P10649582R00	Coverage (\$)	0.00	
	Claim No.	C10017695/JL	Excess (\$)	0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date	26/09/2022	
2. Vehicle Particulars & Condition					
	Make & Model	KIA CERATO FORTE	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	KNAFU411MA5127389	Colour	BRONZE	
	Odometer	168076 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	FIRENZA	6 mm	
	L/H Front Tyre	225/45 R17	FIRENZA	6 mm	
	R/H Rear Tyre	225/45 R17	FIRENZA	6 mm	
	L/H Rear Tyre	225/45 R17	FIRENZA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	23/09/2022	Inspection Date	27/09/2022	
	Survey held at HD PERFECT AUTOWORK PTE LTD				
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	c. Estimate Days of Repair				

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: