



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: SERENE LIM

Ref: CS/INC22009482/Aqy3q2

Date: 01/12/2022

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                 |                |            |
|--------------|-----------------|----------------|------------|
| Insured Veh. | SLG 9448D       | Veh. Inspected | SNA 2767L  |
| Policy No.   |                 | Coverage (\$)  | 0.00       |
| Claim No.    | MT/1189985- 002 | Excess (\$)    | 0.00       |
| Assign From  | ANNIE KOH       | Assign Date    | 27/09/2022 |

### 2. Vehicle Particulars & Condition

|              |               |              |            |
|--------------|---------------|--------------|------------|
| Make & Model | HONDA SHUTTLE | c.c          | 1496       |
| Engine No.   | HIDDEN        | Year of Reg. | 2021       |
| Chassis No.  | GK82102636    | Colour       | BLACK      |
| Odometer     | 18311 KM      | Steering     | IN ORDER   |
| Brakes       | IN ORDER      | Modification | SPORTS RIM |
| General      | GOOD          |              |            |

### 3. Conditions of Tyres

|                | Size       | Make     | Balance |
|----------------|------------|----------|---------|
| R/H Front Tyre | 185/60 R15 | YOKOHAMA | 6 mm    |
| L/H Front Tyre | 185/60 R15 | YOKOHAMA | 6 mm    |
| R/H Rear Tyre  | 185/60 R15 | YOKOHAMA | 6 mm    |
| L/H Rear Tyre  | 185/60 R15 | YOKOHAMA | 6 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

|                |  |                     |                         |
|----------------|--|---------------------|-------------------------|
| Accident Date  | 23/09/2022   | Inspect Date / Time | 27/09/2022 ( 04:16 PM ) |
| Survey held at | JL PERFECT AUTOWORK PTE LTD<br>8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875 |                     |                         |

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**