



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22009483/Any3e2

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 24/11/2022

ATTN: AZHARI AFIDI

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 111U	Veh. Inspected	SLM 1631L
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1182605-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	27/09/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU11204302	Colour	WHITE
Odometer	181867 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	ARIVO	6 mm
L/H Front Tyre	215/60 R16	ARIVO	6 mm
R/H Rear Tyre	215/60 R16	ARIVO	6 mm
L/H Rear Tyre	215/60 R16	ARIVO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/07/2022	Inspect Date / Time	27/09/2022 (04:09 PM)
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**