

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURAN	ICE LTD	Ref:	CS/INC22009485/Aqy3e2	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557	Date:	19/01/2023	
	ATTN: SERENE LI	M	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJV 5015R	Veh. Inspected	SMJ 6956X	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1189272-002	Excess (\$)	0.00	
	Assign From	ANNIE KOH	Assign Date	27/09/2022	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA MOBILIO	c.c	1497	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	MRHDD4870GP000464	Colour	WHITE	
	Odometer	104417 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	185/65 R15	DUNLOP	6 mm	
	L/H Front Tyre	185/65 R15	DUNLOP	6 mm	
	R/H Rear Tyre	185/65 R15	DUNLOP	6 mm	
	L/H Rear Tyre	185/65 R15	DUNLOP	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	18/09/2022	Inspect Date / Time	27/09/2022 ( 12:53 PM )	
	Survey held at	at XIN HUA WORKSHOP PTE LTD			
	23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	6 Work	ing Days	