

Your Ref: NDH 9465

Date: 19<sup>th</sup> Oct 2022

Our Ref: CS1/ICA22009496/Tqy3e2

**M/s Immigration & Checkpoints Authority Singapore**

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: NDH 9465  
ACCIDENT DATE: -**

We thank you for your instruction on 22/09/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of NDH 9465 from M/s Transpart Auto Supply Sdn Bhd.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: NDH 9465
Make & Model	: Scania
Year of Registration	: -
Chassis Number	: -
Engine Capacity	: -

- 2. We recommend that the repairs of the entire damage require about 1 (One) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.