

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: ANG YVONNE Code: ASM 1.
SINGAPORE 068811
1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SMG 2369H Veh. Inspected SMP 8197A Policy No. P2223967 Coverage (\$) 0.00 Claim No. S2M04BOZ Excess (\$) 0.00 Assign From ANG YVONNE Assign Date 27/09/2022 2. Vehicle Particulars & Condition Make & Model MERCEDES BENZ C180 c.c 1595 Engine No. HIDDEN Year of Reg. 2019 Chassis No. WDD2050402R492052 Colour GREY Odometer 51138 KM Steering IN ORDER Brakes IN ORDER Modification STANDARD ALLOY RIM
Insured Veh. SMG 2369H Veh. Inspected SMP 8197A
Policy No. P2223967 Coverage (\$) 0.00 Claim No. S2M04BOZ Excess (\$) 0.00 Assign From ANG YVONNE Assign Date 27/09/2022
Claim No. S2M04BOZ Excess (\$) 0.00 Assign From ANG YVONNE Assign Date 27/09/2022 2. Vehicle Particulars & Condition Make & Model MERCEDES BENZ C180 c.c 1595 Engine No. HIDDEN Year of Reg. 2019 Chassis No. WDD2050402R492052 Colour GREY Odometer 51138 KM Steering IN ORDER Brakes IN ORDER Modification STANDARD ALLOY RIM
Assign From ANG YVONNE Assign Date 27/09/2022 2. Vehicle Particulars & Condition Make & Model MERCEDES BENZ C180 c.c 1595 Engine No. HIDDEN Year of Reg. 2019 Chassis No. WDD2050402R492052 Colour GREY Odometer 51138 KM Steering IN ORDER Brakes IN ORDER Modification STANDARD ALLOY RIM
2. Vehicle Particulars & Condition Make & Model MERCEDES BENZ C180 c.c 1595 Engine No. HIDDEN Year of Reg. 2019 Chassis No. WDD2050402R492052 Colour GREY Odometer 51138 KM Steering IN ORDER Brakes IN ORDER Modification STANDARD ALLOY RIM
Make & ModelMERCEDES BENZ C180c.c1595Engine No.HIDDENYear of Reg.2019Chassis No.WDD2050402R492052ColourGREYOdometer51138 KMSteeringIN ORDERBrakesIN ORDERModificationSTANDARD ALLOY RIM
Engine No. HIDDEN Year of Reg. 2019 Chassis No. WDD2050402R492052 Colour GREY Odometer 51138 KM Steering IN ORDER Brakes IN ORDER Modification STANDARD ALLOY RIM
Chassis No. WDD2050402R492052 Colour GREY Odometer 51138 KM Steering IN ORDER Brakes IN ORDER Modification STANDARD ALLOY RIM
Odometer 51138 KM Steering IN ORDER Brakes IN ORDER Modification STANDARD ALLOY RIM
Brakes IN ORDER Modification STANDARD ALLOY RIM
General GOOD
Contral
3. Conditions of Tyres
Size Make Balance
R/H Front Tyre 245/40 R18 CONTINENTAL 6 mm
L/H Front Tyre 245/40 R18 CONTINENTAL 6 mm
R/H Rear Tyre 245/40 R18 CONTINENTAL 7 mm
L/H Rear Tyre 245/40 R18 CONTINENTAL 7 mm
4. Description of Damages
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
5. General Information
Accident Date 24/09/2022 Inspect Date / Time 27/09/2022 (03:11 PM)
Survey held at ECO AUTOMOBILE CLAIMS & REPAIR PTE LTD
15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417808
5a. Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,300-\$4,300
5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

Report Ref No. CS3/ASM22009497/Sqy3m4

Inspected By

S MOHAMED IRFAN BIN MOHAMED IQUBAL

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 ${\tt BEng(Hons),B.Bus,MBA,PEng,PE,\,MInstAEA,MASME,MIRTE}$

REGD Auto Consultant-SAE, Licensed Appraiser