

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile				
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22009507/Dqy3q2	
	(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date:	23/02/2023	
			Code	: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJJ 6048C	Veh. Inspected	SH 8172S	
	Policy No.	P10446930R02	Coverage (\$)	0.00	
	Claim No.	C10017724/JL	Excess (\$)	0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date	27/09/2022	
2.	. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI IONIQ	c.c	1580	
	Engine No.	HIDDEN	Year of Reg.	2019	

	Make & Model	HYUNDAI IONIQ	c.c	1580
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	KMHC851CVKU146081	Colour	BLUE
	Odometer	346250 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3 Conditions of Tyres				

3.	Conditions of Tyres			
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	5 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	5 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5.	General Information			
	Accident Date	24/09/2022	Inspection Date	27/09/2022
	Survey held at Blk 9 Sector C #01-42, Sin Ming Industrial Estate			
	Repairer	BIFROST AUTO PTE LTD		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

5b.	Estimate Days of Repair
JD.	Latillate Days of Nepall

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days