

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE		Ref:	CS3/ASM22004778/Gty3e2	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811			Date:	31/05/2022
	ATTN: ONG KIAN	THENG DERICK		Code:	ASM
1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SKB 9890Y	Veh. Inspected	k	SX 5603B
	Policy No.	GA591085	Coverage (\$)		0.00
	Claim No.	S2M041M4	Excess (\$)		0.00
	Assign From	ONG KIAN THENG DERICK	Assign Date		20/05/2022
2. Vehicle Particulars & Condition					
	Make & Model	AUDI A3 SPORTBACK 1.0	c.c		999
	Engine No.	HIDDEN	Year of Reg.		2018
	Chassis No.	WAUZZZ8V3JA080338	Colour		BLUE
	Odometer	68069 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/55 R16	MICHELIN		6 mm
	L/H Front Tyre	205/55 R16	MICHELIN		6 mm
	R/H Rear Tyre	205/55 R16	MICHELIN		6 mm
	L/H Rear Tyre	205/55 R16	MICHELIN		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
5.	General Information				
	Accident Date	17/05/2022	Inspect Date /	Time	20/05/2022 ( 05:30 PM )
	Survey held at	2 KAKI BUKIT AVE 2 #01-33, KA	KI BUKIT AUTOH	IUB	
	Repairer WILLIAM LEE CAR AIR CON ENGINEERING				
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				

Report Ref No. CS3/ASM22004778/Gty3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

**REGD Auto Consultant-SAE, Licensed Appraiser** 

**Automotive Assessor**