

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	STRIDES AUTOM	OTIVE SERVICES PTE LTD		Ref:	CS/SMR22009544/Eny3e2	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 37705		Date:	10/11/2022	
				Code:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHD 6237D	Veh. Inspected	ł	SMR 2536J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/09/22/2064	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		27/09/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	B.M.W. 216D	c.c		1499	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	WBA2X920X07F16234	Colour		ORANGE	
	Odometer	30115 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	MICHELIN		5 mm	
	L/H Front Tyre	215/60 R16	MICHELIN		5 mm	
	R/H Rear Tyre	215/60 R16	MICHELIN		5 mm	
	L/H Rear Tyre	215/60 R16	MICHELIN		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	24/09/2022	Inspection Dat	e	18/10/2022	
	Survey held at	PERFORMANCE MOTORS LTD				
		303 ALEXANDRA ROAD SINGAPORE 159941				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:		3 Worki	ing Days	
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					