

A.S.S. REC. BY:

REF:

CS3/CT122009553/Rny3

193B

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLF 9042Xat Workshop m/s Seny Hungeof 1018, MISTHUN Rd PK A #01-350Insured: CTI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 63k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLF 9042X Yr Regn: 2016 / SEPType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA COROLLA 1.6 VTEC 1598Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: 70603 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRO53 REH 104552481Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 215/452R17R: 1.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAKEFront 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 25/09/22 D.O.I. 28/09/22Survey held at Seny HungeDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIM IT - 29K

ESTIMATE RANGE OF REPAIR / no. of days - (2K-3K) / 6 days

03/10/22 submit PRS report/repair range: \$2k-&3k and 6 days

Date/Time, File Pass to?

☐ : Preli. Report

1) 03/10/22

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Rep. Form: PRS

Lump Sum / L.B. (\$) _____

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 193B

Vehicle Details

Vehicle No.: SLF9042X
Vehicle to be Exported: No
Intended Deregistration Date: 30 Sep 2022
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 CVT
Primary Colour: Black
Manufacturing Year: 2016
Engine No.: 1ZRY302960
Chassis No.: MR053REH104552481
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$19,990.00
Original Registration Date: 15 Sep 2016
First Registration Date: 15 Sep 2016
Transfer Count: 1
Actual ARF Paid: \$19,990.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 Sep 2026
PARF Rebate Amount: \$12,993.00

Intended COE Rebate Details

COE Expiry Date: 14 Sep 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$52,503.00
COE Rebate Amount: \$20,767.00
Total Rebate Amount: \$33,760.00

The information contained herein is correct as at 30 Sep 2022

OK

Toyota Corolla Altis 1.6A

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price **\$67,050**

Depreciation **\$13,440 /yr**
[View models with similar depre](#)

Reg Date 28-Dec-2016
(4yrs 2mths 27days COE left)

Mileage 70,000 km (12.2k /yr)

Manufactured 2016

Road Tax \$742 /yr

Transmission Auto

Dereg Value \$35,090 as of today ([change](#))

OMV \$19,990

COE \$50,389

ARF \$19,990

Engine Cap 1,598 cc

Power 90.0 kW (120 bhp)

Curb Weight 1,215 kg

No. of Owners 2