

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS/SMR22009573/Svy3m4	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 17705		Date:	27/10/2022	
				Code:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHB 226K	Veh. Inspected		SGC 8949L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/09/22/2061	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		28/09/2022	
2. Vehicle Particulars & Condition						
	Make & Model	LEXUS GS200T	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JTHBA1BL10A000875	Colour		SILVER	
	Odometer	147576 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	245/35 R19	MICHELIN		6 mm	
	L/H Front Tyre	245/35 R19	MICHELIN		6 mm	
	R/H Rear Tyre	245/35 R19	MICHELIN		6 mm	
	L/H Rear Tyre	245/35 R19	MICHELIN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	24/09/2022	Inspection Date	9	29/09/2022	
	Survey held at	Repairer 2 Kaki Bukit Ave 2 Autohub #01-14 (S) 417921 S3 AUTO WORKSHOP				
	Repairer					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				