

ASS. REC. BY:

REF: 072 / 22009604 / KV

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s 1 Hmk

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SME 2438C Yr Regn: 09, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon

Make: Honda Free c.c. 1496

Colour: M. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 55758 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GB7 1067649

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 185/65R15

R: _____

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 19/9/22 D.O.I. 19/10/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

: Prell. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

\$ + RS. SI

Fixtures

Others

TOTAL

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: TP-GBF 8545L
 Repairer Reference: 73045
 Date calculated: 28/09/2022 4:25 PM

Full Report
 Registration: SME 2438C
 Printed: 28/09/2022 4:25 PM

Summary Information

Claim Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-GBF 8545L	Date of Incident:	14/09/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle Manufacturer:	HONDA		
Model:	FREED (GB3)		
Sub Model:	G		
Model Sheet Number:	35 FD 07		
Registration:	SME 2438C		
VIN number:			
Odometer:	55298		
Model Specs			
AIR CONDITIONING	FOG LAMPS	1.5 LTR 65 KW	TYRES 185/65 HR 15
TWO COAT METALLIC	PREPARE OFF VEHICLE		

Not withered
Repairing B4 paint
3 days

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	R + R FRONT BUMPER		1.0	4.20
NO NUMBER	R + R FRONT BADGE		1.0	4.20
NO NUMBER	R + R RADIATOR GRILLE TRIM		2.0	8.40
NO NUMBER	R + R LEFT HEADLAMP		2.0	8.40
NO NUMBER	R + R RIGHT HEADLAMP		2.0	8.40
0283	FRONT BUMPER REPAIR		10.0*	42.00
0475	L/BONNET HINGE REPAIR		5.0*	21.00
0476	R/BONNET HINGE REPAIR		5.0*	21.00
1009	FRONT PANEL CPL REPAIR		30.0*	126.00
Labour Cost			Hrs	WU
Panel / Mechanical Labour			5.80	58.0
Total of Labour				243.60
				243.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- Subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	FRONT BUMPER REPAIR PAINT PLASTIC		14.0	
	FRONT PANEL CPL SURFACE PAINT		6.0	

Paint Material Per Part			Price SGD
Code	Description		
0283	FRONT BUMPER REPAIR PAINT PLASTIC		40.50
1009	FRONT PANEL CPL SURFACE PAINT		11.21

Labour Cost - Paint		Hrs	WU	Price SGD
Factor		42.00		SGD/h
Time Paint			20.0	
Preparation Main Work Metal		0.50	5.0	21.00
Preparation Comp. Work Plastic		2.50	25.0	105.00
Total		5.00	50.0	210.00

Material Cost - Paint		Price SGD
Repair Painting Plastic		40.50
Surface-/Blend Paint		11.21
Material-constant Metal		9.00
Material-constant Plastic		28.60
Total		89.31

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
0431	GRILLE BADGE	75700TF0000	Original		20.00
0414	GRILLE MOULDING	71123SYYZ01	Original		550.00
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				570.00
u: Used parts	Fixed Sundry Parts Price				100.00
	Total				670.00

Cost Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	570.00	
Total Parts	100.00	670.00
Labour Time Base 10 WU/h		
Total 58.0 WU X 42.00 SGD/h		
Total of Labour	243.60	243.60
Paint Work Time Base 10 WU/h		
Labour Cost 50.0 WU X 42.00 SGD/h		
Material Cost	210.00	
Total Paint Including Material	89.31	299.31
Repair Cost Excludes GST		1,212.91
GST (+7.0%)		84.90
Repair Cost Included GST		1,297.81

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/09/2022 13:59 (SGT)
Reported by	Owner
Date of Accident	14/09/2022 18:15 (SGT)
Exact Location of Accident	Ang Mo Kio Ave 5, Singapore
Additional Location Information	Block 521 open space carpark
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME2438C
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	KHOO TECK PING
NRIC No	SXXXX372C
Email Address	armour23@yahoo.com
Mobile Phone No	(Phone) +65-97312347
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Freed
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	1800133303-04

DRIVER

Name of Driver	SEAH XIN YI
NRIC No	SXXXX841G
Date Of Birth	08/11/1982
Occupation	Indoor

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the incident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the At-Fault Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and completion of this form by insurance companies is not an admission of liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the G.A. Claims Management Centre established by the General Insurance Association of Singapore (GIAS) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore (GIAS) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the **Personal Information**) and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers) who have insured vehicles involved in this accident shall be collectively referred to as the **Insurers**, the insurers, lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:

(i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquires by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the **Purposes**).

All insurers who have insured vehicles involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect and disclose and/or process my Personal Information for one or more of the above Purposes, and my Personal Information may be disclosed by any of the insurers and/or GIAS to their third-party service providers or agents (including their lawyers/law firms) which may be based outside of Singapore, for one or more of the above Purposes.

18 Sep 2022
12:13 pm

Witnessed by Repeating Under-Engineer
Name: SOH JIT HOON

Sketch Plan

