

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMG 6604C Yr Regn: 28/12/18Type: ☒ M.Cap / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: BMW 420i c.c. \_\_\_\_\_Colour: Blue A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 34114 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: \_\_\_\_\_

C/No: WBADH1320908P2414Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☐ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☐ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☐ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: 225/45R18R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pirelli

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 24/9/22 D.O.I. 24/9/22Survey held at PerformanceDes. of Damages ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-153K</u>

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: \_\_\_\_\_

1) \_\_\_\_\_

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / I.B.F. (\$) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL


## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Page No. : 1 of 7

Estimate No. : b1 63456  
Date Estimated : 27/09/2022  
Prepared By : Yap Mee Key

## - ESTIMATE REPAIR FOR -

Chin Yoke Ching  
109C Edgedale Plains  
#14-133

Singapore 823109

## - ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG6604C	WBA4H32090BP28474	28/12/2018	420i GC	33823

DESCRIPTION	VALUE
To replace front wall, bonnet and front both side panel. <i>LH 1</i> <i>4 x 850</i>	<del>3440</del> X 6,375.00
To respray bonnet, front bumper, front both side panel and a pillar both side. <i>Don't Front LH - 1</i>	4741 ✓ 5,192.00
To tow accident vehicle to PML workshop.	150.00 ✓
To supply front or rear emboss number plate. <i>07</i> (Special type).	165.00 ✓
To replace radiator assembly, fan housing with fan including pressure test, bleed cooling system and conduct check for leak. (All models except 7 series). <i>784</i>	X ? 826.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).	X 531.00
To replace both front left and right pneumatic spring strut including reset and check function of ride level height control for proper function.	X 858.00
To conduct chassis alignment measuring check using Car-O-Liner measuring system accordance with BMW specification.	? X 531.00
To replace front windscreen glass.	X 574.00
To remove and install IU unit bracket.	X 31.00
To conduct water leak tests.	X 75.00
To check electrical.	168 ✓ 177.00
To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.	X 531.00



## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 63456  
Date Estimated : 27/09/2022  
Prepared By : Yap Mee Key

Page No. : 2 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG6604C	WBA4H32090BP28474	28/12/2018	420i GC	33823

## DESCRIPTION

## VALUE

To replace both left and right headlights. (brazing) 795 ✓ 837.00

To replace air con condenser and air con hose including vacuum system, top up freon gas and conduct check for leak. (For all models except for 7 series). 952 ? X 1,003.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function. 168 ✓ 177.00

To carry out body cavity preservation. (Per panel). 1x 442 X 118.00

Sundries. 150.00

Total Labour 1: 18,301.00

DESCRIPTION	QTY	PRIC	VALUE
BLIND RIVET / MC	20	1.50	30.00 ✓
C CLIP FOR PLASTIC NUT / MC	20	1.10	22.00 ✓
RADIATOR ? BT	1	836.85	836.85 ✓
ROCK GUARD ? BR	2	68.30	136.60 ✓
COVER TOP X NN	1	64.25	64.25
COVERING LOWER ? X NN	1	73.50	73.50
RADIATOR ? BT	1	836.85	836.85 ✓
FAN HOUSING WITH FAN 400W ? X NN	1	1,189.65	1,189.65
FAN SHROUD 400W/600W ? X NN	1	289.00	289.00
FRT SPRING STRUT ? X NN	2	530.10	1,060.20
BONNET / MC	1	1,312.90	1,312.90 ✓
FRT LH SIDE PANEL / MC	1	716.75	716.75 ✓
FRT LH SIDE PANEL X NN	1	716.75	716.75 ✓
FRT LH 2 SIDE PANEL BRACKET / MC	1	41.20	41.20 ✓
FRT RH 2 SIDE PANEL BRACKET X NN	1	41.20	41.20
FRT LH 1 SIDE PANEL BRACKET ? BT	1	102.95	102.95 ✓
FRT RH 1 SIDE PANEL BRACKET X NN	1	102.95	102.95
FRT LH 3 SIDE PANEL BRACKET ? X NN	1	41.20	41.20
FRT RH 3 SIDE PANEL BRACKET X NN	1	41.20	41.20
BONNET LH HINGE X NN	1	110.10	110.10
BONNET RH HINGE ? X NN	1	110.10	110.10
FRT BUMPER TOP CARRIER / MC	1	419.45	419.45 ✓
FRT LH DEFORMATION ELEMENT / MC	1	112.95	112.95 ✓
FRT SHOCK ABSORBER / MC	1	63.05	63.05 ✓
LH FOG LAMP SUPPORT / MC	1	43.45	43.45 ✓
RH FOG LAMP SUPPORT ? BR	1	43.45	43.45 ✓
SUPPORT CENTRAL / MC	1	14.15	14.15 ✓
LICENCE PLATE BASE ECE / MC	1	70.95	70.95 ✓

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 63456  
Date Estimated : 27/09/2022  
Prepared By : Yap Mee Key

Page No. : 3 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG6604C	WBA4H32090BP28474	28/12/2018	420i GC	33823

DESCRIPTION	QTY	PRIC	VALUE
MOUNTING SUPPORT <i>C X NN</i>	1	16.25	16.25
COVER LOWER PART CENTRE <i>BR</i>	1	44.75	44.75 ✓
FRT PANEL BUMPER PRIMED (BASIS) <i>BR X NN</i>	1	1,084.65	1,084.65 ✓
FLAP TOWING EYE PRIMED <i>BR X NN</i>	1	44.35	44.35 ✓
SET MOUNTING PDC/PMA SENSOR FRT <i>BR X NN</i>	1	78.20	78.20 ✓
SET MOUNTING PDC/PMA SENSOR FRT <i>BR X NN</i>	1	78.20	78.20 ✓
LH PARTIALLY OPEN GRID (SPORT/LUXUR <i>BR</i>	1	92.30	92.30 ✓
RH PARTIALLY OPEN GRID (SPORT/LUXUR <i>BR</i>	1	92.30	92.30 ✓
Closed grid, <i>BR X NN</i>	1	92.30	92.30 ✓
Closed grid, <i>BR X NN</i>	1	92.30	92.30 ✓
LH TRIM SPORT LINE <i>BR</i>	1	125.80	125.80 ✓
RH TRIM SPORT LINE <i>BR</i>	1	125.80	125.80 ✓
FINISHER ROD CENTRE (SPORT LINE) <i>BR</i>	1	54.15	54.15 ✓
INSERT AIR INLET MIDDLE (LINES) <i>BR</i>	1	153.85	153.85 ✓
FRT LH GRILLE (SPORT) <i>BR</i>	1	135.15	135.15 ✓
FRT RH GRILLE (SPORT) <i>BR</i>	1	131.20	131.20 ✓
CLIP <i>BR</i>	5	1.10	5.50 ✓
GAS STRUT HOOD <i>X NN</i>	2	127.15	254.30 ✓
STOP BUFFER <i>X NN</i>	2	13.05	26.10 ✓
GREEN WINDSCREEN <i>X NN</i>	1	817.35	817.35 ✓
COVER WINDSCREEN TOP <i>X NN</i>	1	38.55	38.55 ✓
BUMP STOP <i>NN</i>	10	3.30	33.00 ✓
EXPANDING RIVET D=8MM <i>X NN</i>	20	1.10	22.00 ✓
FRONT PANEL V STRUT <i>BT</i>	1	120.75	120.75 ✓
FRT BUMPER LOWER MOUNT <i>BR</i>	1	135.10	135.10 ✓
LH HEADLIGHT BRACKET <i>BR</i>	1	15.00	15.00 ✓
RH HEADLIGHT BRACKET <i>BR</i>	1	15.00	15.00 ✓
FRONT CROSSLINK <i>BT</i>	1	181.10	181.10 ✓
AIR DUCT BOTTOM <i>BR</i>	1	102.40	102.40 ✓
AIR DUCT RADIATOR <i>BR</i>	1	107.50	107.50 ✓
AIR DUCT BRAKE LH <i>BR</i>	1	69.35	69.35 ✓
AIR DUCT BRAKE RH <i>BR</i>	1	69.35	69.35 ✓
FRT END SUPPORT <i>BR</i>	1	24.40	24.40 ✓
ADJUSTER <i>MIS</i>	1	5.80	5.80 ✓
FRONT ENGINE HOOD SEALING <i>BR</i>	1	39.85	39.85 ✓
LH ENGINE HOOD SEALING <i>X NN</i>	1	39.85	39.85 ✓
RH ENGINE HOOD SEALING <i>X NN</i>	1	39.85	39.85 ✓
Holder <i>X NN</i>	1	4.25	4.25 ✓
LH HEADLIGHT LED TECHNOLOGY <i>BR</i>	1	2,726.25	2,726.25 ✓
RH HEADLIGHT LED TECHNOLOGY <i>BR</i>	1	2,726.25	2,726.25 ✓
LH FOG LIGHT LED <i>BR</i>	1	467.55	467.55 ✓
RH FOG LIGHT LED <i>X NN</i>	1	467.55	467.55 ✓
DECOUPLING RING PDC TORQUE CONVERTE <i>BR</i>	4	5.30	21.20 ✓
PDC SENSOR IMPERIAL BLUE (A89) <i>BR</i>	4	373.90	1,495.60 ✓

Total Parts : 21,172.45



**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : b1 63456  
Date Estimated : 27/09/2022  
Prepared By : Yap Mee Key

Page No. : 4 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG6604C	WBA4H32090BP28474	28/12/2018	420i GC	33823

Steve (LKK)  
29/9/22, 1.93p

OD- N/A PL  
Excess- ?  
P/P  
by BL by  
8 dys



Labour 1	:	18,301.00
Parts	:	21,172.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,763.14
Grand Total	:	<u>42,236.59</u>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	21/09/2022 16:39 (SGT)
Reported by	Both
Date of Accident	20/09/2022 21:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	CTE
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG6604C
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHIN YOKE CHING
NRIC No	SXXXX644E
Email Address	caslynxc@gmail.com
Mobile Phone No	(Phone) +65-84883626
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	BMW
Model	420i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1998

#### INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMPCSNW00238792101

#### DRIVER

Name of Driver	CASLYN CHUA MAN LYN
NRIC No	SXXXX371C
Date Of Birth	22/11/1996
Occupation	Indoor

Date Of Driving Pass .....	24/01/2018
Driving experience .....	4 YEARS AND 8 MONTHS
Gender .....	Female
Mobile Number .....	(Phone) +65-81827076
Alt. Phone Number .....	-
Email Address .....	caslynxc@gamil.com
Address .....	BLK 109C EDGEDALE PLAINS #14-133
Address complement .....	-
Postcode .....	823109
Is the driver the policyholder? .....	No
If No, Relationship of the Driver with the Insured .....	Child
Does Driver Own Other Vehicles? .....	No
Vehicle Registration Number of Other Vehicle Owned by Driver .....	-
Insurance Company of Other Vehicle Owned by Driver .....	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....	Chain Collision
Weather Conditions .....	Clear
Road Surface .....	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....	No
Number of vehicles involved in the accident .....	3
Was anybody injured in the Accident? .....	No
Was any injured conveyed to hospital by ambulance? .....	-
Was any other vehicle or property damaged? .....	Yes
Number of Passengers (Including Driver) .....	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....	No
Translator's name .....	-
Translator's ID .....	-
Translator's phone number .....	-
Translator's email .....	-
Original language used in the statement .....	-

#### PASSENGER 1

Name .....	NIKKOLYNN BELINDA
Gender .....	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....	No
Was notice of intended Prosecution given? .....	No
If yes, against whom? .....	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER ATTACH

#### ATTACHMENT(S)

Are accident photos available for attachment? .....	Yes
Was there any video captured by Car Camera? .....	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number .....	SMU2522H
Vehicle Manufacturer .....	-
Vehicle Model .....	-
Vehicle Variant .....	-





Vehicle Colour .....	Red
Vehicle Category .....	Private car
Name of Driver .....	ONG GAY HUA
NRIC No .....	SXXXX505B
Contact Number .....	(Phone) +65-91917202
Address .....	-
Address complement .....	-
Postcode .....	-
Insurance Company Name .....	-
Nature Of Damage .....	-
Details of property damaged in accident .....	-
No. Of Passenger (Including Driver) .....	-

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number .....	SKQ8384U
Vehicle Manufacturer .....	-
Vehicle Model .....	-
Vehicle Variant .....	-
Vehicle Colour .....	Gray
Vehicle Category .....	Private car
Name of Driver .....	ONG POH HENG
NRIC No .....	SXXXX277I
Contact Number .....	(Phone) +65-94888134
Address .....	-
Address complement .....	-
Postcode .....	-
Insurance Company Name .....	-
Nature Of Damage .....	-
Details of property damaged in accident .....	-
No. Of Passenger (Including Driver) .....	-



SKETCH PLAN

BEFORE  
AMK AVE 1



1ST LANE



A SMG 6604C

B SMU 2522H

C SKR 8384U

LTE HIGHWAY

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AT LTE BEFORE AMK AVE 1, ONE CHAIN ACCIDENT ~~HAD~~ HAD ALREADY  
OCCURRED. I WAS THE BRAGG & CHASED THE CHAIN ACCIDENT I WAS IN.  
POLICE & AMBULANCE WAS INVOLVED BUT NO CHARGES WAS CHARGED  
BECAUSE NO ONE WAS INJURED.

DECLARATION

I/We declare the foregoing particulars are true in every respect

②

Policyholder's Signature  
Date & Time:

②

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/IN No.:


**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

①   
 Policyholder's Signature  
 Date & Time:

②   
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

③   
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.: