



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOH CYNTHIA		Ref: CS/ASM22009630/Ucy3m4 Date: 13/10/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 2981U	Veh. Inspected	SKD 444B
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S2M04BX0	Excess (\$)	0.00
Assign From	LOH CYNTHIA	Assign Date	29/09/2022
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E200 (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2120342B118205	Colour	BLUE
Odometer	118794 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40ZR18	CONTINENTAL	6 mm
L/H Front Tyre	245/40ZR18	CONTINENTAL	6 mm
R/H Rear Tyre	245/40ZR18	CONTINENTAL	6 mm
L/H Rear Tyre	245/40ZR18	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/09/2022	Inspection Date	29/09/2022
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	