LA DIS	SIGNMENT
From: Date:	Veh No: SM5302 Yr Regn: 2018, Oct
Estimated Cost:	Type: M.Car / M.Cycle Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Yunaha YISZR c.c 150.
at Workshop m/s	Colour Black A/C: Insured / Std / NI / NA
of	Sp.Reading T/Radio: Insured / Std / NI / NA
insured:	Eng/No:
Policy No.	C/No: PMY490510J01944 19.
Claims No.	Gen. Cond. Good/ Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modí: Nil /S/Rim STD A/Rim or
	Tyre Size: F: 80/80R17
(Policy Condition)	R: 90/80R17
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 06 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. mm L/Bal. / mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 30/09/22
Lum Sum: % 3 Val.: Yes or No	Survey held at Ong Moloc.
CA / REV / REP. / 24 HRS	Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT Date: Person Contacted:	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collisio
TP Sonpo.	
mv: 8000 RM.	
PV: 500 RM.	
Nett: 7500 RM 2 \$2.5 K.	
	•
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
) Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:

Learning France L. R. D. C. Per





Report No. T/20220915/2129

Police Station Of Origin: Jurong East N.P.C 92 Boon Lay Way SINGAPORE 609962 Tel No: 1800-8999999

REPORT O	F A IKATTIL	ACCIDENT			
Date/Time Report Made: 15/09/2022 11:48			Vide Report No.: D/20220914/0042	Station Diary No. 32	
Informa	it's Particu	lars		athan it committee and the second	
		FUDDIN BIN	Address:		
ID Type / ID No.: FIN NO / G2126028U		Contact No.: Home/Office: Mobile: 81871538			
National MALAYS	4		Email:		
Sex: Male	Age:	Date of Birth: 23/06/1991	Type of Informant: Rider		
Race: Malay		Language:	Institution / School Name:		
Occupation: Lorry driver			Driving Licence Information: Class: 2B,3,4A Date of Expiry: 02/08/202		

Type of Accident: Accident: Injury Attended by Police		Drink Drive: No	Date/Time of Accident: 14/09/2022 11:30	Type of Location X-Junction	
Location: JALAN AHM	AD IBRAHIM	Dood Surface:		Road Speed Limit:	
Weather: Clear		Road Surface: Dry			
Traffic Flow:		Traffic Control:	Management	Traffic Volume: Heavy	
		Type of Collision: Between Moving Vehicles - Head To Side			

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLD8651E	Car				Slightly Damaged	0
SM5302	Matorcycle				Seriously Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





Police Station Of Origin: Jurong East N.P.C 92 Boon Lay Way SINGAPORE 609962 Tel No: 1800-8999999 2 of 3 Report No. T/20220915/2129

CONTINUATION OF REPORT

Nama	NIANITA CODILA MAGI	t a t	***************************************		***********	Name of the State of the State of the State of State of the State of State
Name	NANTASOPHA JARIN			ID No.		G3297895P
Related Vehicle	SLD8651E (Car)			Contact No.		98304293
Hospital/Clinic	NIL			Class Drivin Licent Expiry	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Disc	harge	NIL		
No. of Days granted Medical Leave NIL		NIL	Degree of		NIL	
Rider				M 2 E		
Name	MUHAMMAD SHAHFUDDIN BIN MAHMOR		ID No.		G2126028U	
Related Vehicle	SM5302 (Motorcycle)			Contact No.		81871538
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL			Class of Driving Licence & Expiry Date		Class: 2B,3,4A Date of Expiry: 02/08/2023
Date Treatment	14/09/2022		Date Disc	harge	15/09	/2022
No. of Days gran	ted Medical Leave	15	Degree of		Serio	IIS .

Brief Details.

On 14/09/2022 at about 1130hrs, I was driving my vehicle bearing registration number SM5302 along Jalan Ahmad Ibrahim towards Tuas at the cross junction of Jalan Ahmad Ibrahim and Jurong Pier Rd on the left lane as the traffic light had turned green. However, there was a red car bearing registration number SLD8651E on the left lane of Jurong Pier Rd that did not give way to me despite it being my right of way. Subsequently, the front wheel of my vehicle collided against the right side of the car. Due to the impact, I was thrown off my motorcycle and landed on my left side. I broke my left arm and left leg along with some scratches on my right hand and left knee. I was informed by a passer-by that they have contacted Police and ambulance. I was conveyed by Ambulance to Ng Teng Fong General Hospital and received 15 days of MC from 14/09/2022 to 29/09/2022.

My address is: No. 6 Jalan Anggerik 5/8 Taman Anggerik 81200 Johor Bahru Johor



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

No. Pendaftaran'

: SMESQ2

No. iù

: 910623016395

Nama Pemunya Bardaftar

: MUDAMMAD SHARFUDDIN BIN MARMOR

I NO S CALAM ANGGERIK 5/8 TAMAM ANGGERIK

31200 JOHOR BAHRU JOHOR

No. Chasis/No. Engin

: PMYU30513J0194413 . 33D3E-194439

Bustan Nama Model

: YAMAHA : YAMAHA Y1EZR

Keupaysan Enjin

: 1,50

Bahan Bakar

: PETROL

Status Asal

: PEMASANGAN TEMPATAN

Kelas Kegunaan

: MOTOSIKAL

Jenis Badan/Tahun Dibuat D MOTOSIKAL / 2018

: 20/10/2018

Tarikh Pendaftaran B. D. M/B. G. K/BTM

Syarat Pendaftaran 1

Syarat Pendaftaran 2


Syarat Pendaftaran 3

LESEN KENDERAAN MOTOR

MOTOSIKAL No.SIRI: BD 989975 19 OKT 2022

: 21 MV1797949

CAP MESIN PENERIMAAN JABATAN PENSANGKUTAN JALAS 02



Yamaha y15 - Found 466 All Categories in Entire Malaysia - Page 1 of 12 Home > Entire Malaysia > All Categories

