



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22009637/Kvy3q2 Date: 11/11/2022 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJQ 4322L	Veh. Inspected	YN 6538G	
Policy No.	P10362137R02	Coverage (\$)	0.00	
Claim No.	C10017698/CH	Excess (\$)	0.00	
Assign From	SALIZAWATI HAIZAR	Assign Date	29/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	HINO 300 (M)	c.c	4009	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JHHUCS3H50K009865	Colour	WHITE	
Odometer	413138 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	700 R16X10	SWALLOW	8 mm	
L/H Front Tyre	700 R16X10	SWALLOW	8 mm	
R/H Rear Tyre	700 R16X10 (D)	KENDA	7/7 mm	
L/H Rear Tyre	700 R16X10 (D)	KENDA	7/7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/09/2022	Inspection Date	02/11/2022	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	