

Vehicle Damage Assessment Report for [GBD6628C]

Estimate Created: 19/04/2023 15:19 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 19/04/2023 15:31 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number	SG1143533
Claim Type	TP		
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number	

Vehicle Information

Brand	Renault	Model	Grand Scenic
Engine Type			
License Plate Number	GBD6628C	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- VEHICLE MAKE AND MODEL: RENUALT MASTER	Insurlogic 4 (19/04/2023 15:31)
- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK: CONCLUDED THE COST OF REPAIR AT \$3,600.00 WITH 3 WORKING DAYS	Insurlogic 4 (19/04/2023 15:29)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
Headlamp LH		1	933.50	-10.00 %	840.15
Front bumper		1	912.82	-10.00 %	821.54
Front bumper clips		6	3.50	-10.00 %	18.90
Bonnet		1	1758.50	-10.00 %	1,582.65
Front grille		1	540.05	-10.00 %	486.05
Front grille emblem		1	120.70	-10.00 %	108.63

Parts Subtotal 3,857.92

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
Headlamp wiremesh LH		1.0	90.00	0.00 %	90.00
Bonnet sticker - Certis		1.0	100.00	0.00 %	100.00

Materials Subtotal 190.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	400.00	0.00 %	400.00
To checking wiring	RnR	30.00	0.00 %	30.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	250.00	0.00 %	250.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 430.00

Paint Labor Subtotal 250.00

Labor Subtotal 680.00

Summary

Repair Cost 4,727.92

Discount(23 %) (1,087.42)

3,640.50

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal	3,640.50
----------------	----------