

REF: CS1/LIP22009651/Kvy3

Special Instruction:

LS : 12750 / 9 DAYS

Third Parties:

Claimant:

Surveyor: AUTO PERFORMANCE  
APPRAISAL;

Workshop: T & S MOTOR SERVICE

From (Person): ESTHER CHEAH of LIBERTY Date/Time: 30/09/2022

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

ASSIGNMENT (Office)

### OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SLH 8740K Insured: SNC 4609L

at Workshop m/s T & S MOTOR SERVICE

of BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-357 SINGAPORE 569538

Policy No: \_\_\_\_\_ Claim No: AVS22/1658

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 18/06/2022  
(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT \_\_\_\_\_

Date/Time: \_\_\_\_\_ Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_ days (Red S \_\_\_\_/\_\_\_\_%; Original! \_\_\_\_ days)

Date/Time: 9/11/22 Submit Final Fig LS \$9900, 8 days (Red \$2850 / 22%; Original 9 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	
--	--

**Para(3) : Nett Value**

Market Value : \_\_\_\_\_

Salvage Value : \_\_\_\_\_

Nett Value : \_\_\_\_\_

Inspected/  
Evaluated by:

*Fee Charged:*

Basic &amp; Add

Transport

## Photos

Others

Total

Date: \_\_\_\_\_

1) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

2) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

4) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

6) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_