AH LIM MOTOR COMPANY KV 

SURVEYOR COPY

M/S: DENG CHEN

1 MARY MOUNT TERRACE

5

Not botheried Policy No: P10675683R00
Veh Reg No: SMC7158M
VolksWAGEN PASSAT

3- day,

Estimate No: MCS1900724 Date:

23 Sep 2022

ATTN:

SMC7158M

Your Ref No: Claim Type: Accident Date:

Third Party 22/09/2022 TP Veh Reg No: SJN4210S

83909.72

air Cost to Vehicle No :SMC7158M

Т	Description	Estimate Repair Cost to Venicle No	Quantity		List Price		Amount
S 1 F	PARE PARTS FRONT FENDER LH	1009-20	A 1	PC PO	B1 1	<u>\$\$</u> ,009.70	and and a
3 H 4 F		2330-64 R SIDE CHROME MOULDING LH	00/1341	PC		2,330.67 148.21 2,139:60	information win
5 F	RONT-ALLOY-RIM-LH-	generation described in the half all the least assessment price in the least and the least assessment as the least	Less 10			7,958.88	7,162.99
; T(	ABOUR  CHECK WIRING AND	DUR HECK WIRING AND REFOCUS HAEDLAMP ISMANTLE AND REPLACE DAMAGE PARTS, TO KNOCK, REPA		PC PC		20.00 550.00	3501
Al	O BINDANT AREA LIGN FRONT AFFECTED AREA O SPRAY FRONT BUMPER AND FRONT FENDER LH			IPC _		550.00	40d 1,120.00
					Tot	al	S\$ 8,282.99
				Add GST @ 7%		579.81	
			Total	Total Amount Payable		\$\$ 8,862.80	

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND EIGHT HUNDRED SIXTY TWO AND CENTS EIGHTY ONLY

Plany Taylu Chu. For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: