

AS.S. REC BY: Taufik

REF:

CS / TM 1 22009661 / Tg 33

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / Ws / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: Turner

Vehicle: IN / OUT

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Veh No: SH73426K Yr Regn: 2019 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai C.C. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 569847 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KM H0851CVK 4145767

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wentake

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 3/10/22

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Date/Time, File Pass to? ☐ : Preli. Report

1) 09/11 Typist ☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Days Of Repair: 2

Resurvey No. of Trip: 1

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Report Format: MER-TP

Lump Sum / 900

\_\_\_\_\_

\_\_\_\_\_

## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER:**  
**CTPL**

**Tokio Marine Insurance Singapore Ltd (HQ)**

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	30/09/2022
Vehicle Reg. No.:	<b>SHA3426K</b>	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	03/05/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU209657	Chassis No:	KMHC851CVKU145767
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

**COST OF CLAIMS**

	<b>Amount</b>
Parts	1,235.96
Miscellaneous Items	11.00
Labour	750.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>1,996.96</b>
<b>+ GST 7.00% (S\$)</b>	<b>139.79</b>
<b>Nett Amount (S\$)</b>	<b>2,136.75</b>

**This claim is handled by: JUMANI BIN MASUDIN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 30 Sep 2022)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA3426K/30/09/2022 10:56**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	20.00	0.00	Rp *459.40 FL
2	10		*REAR BUMPER CLIPS	20.00	0.00	net *22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	de *451.25 FL
4	1		*REAR BUMPER BEAM	20.00	0.00	? *394.80 FL
5	1		*REAR BUMPER MAT	0.00	0.00	n *50.00 F
6	1		*REAR BUMPER LOWER MOULDING	20.00	0.00	de *155.00 FL

F=Franchise part, L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>1,532.45</b>
<b>- List Item Discount on L Items (S\$)</b>	<b>296.49</b>
<b>Total Parts (S\$)</b>	<b>1,235.96</b>

ComfortDelGro Engineering Pte Ltd/SHA3426K/30/09/2022 10:56. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	400.00
2	SPRAYPAINT	New	300.00
3	REMOVE/REFIX REVERSE SENSOR	New	50.00
Gross Labour Cost (S\$)			750.00

ComfortDelGro Engineering Pte Ltd/SHA3426K/30/09/2022 10:56. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97415749  
WP 3/10/22 315pm  
L/S Roomy after repair  
tanpin@lkhants.com  
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date/Time: 30.09.2022 10:43

Page : 1

um: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO 305531821

TOMER

AS COMFORT TRANSPORTATION PTE LTD

TOMER NO. 7010045

RESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(P) (O)

OUNT CARD NO.

REGN NO.

SHA3426K

MILEAGE

MAKE

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN 30.09.2022 09:10

YR OF MANU.

03.05.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU145767

COMPLETION DATE/TIME:

JOB DESCRIPTION


cident Date: 30.09.2022

TURE: 3P.30.09.22

NO

LABOR CODE

DESCRIPTION



OKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ledgement Slip

Exit Pass

No.: SHA3426K

JU TOKIO

Vehicle No.:

SHA3426K

f Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard