

ASS. REC. BY:

REF: C12/

CS/CTI22009684/Kqy3

Kenneth

ASSIGNMENT

SGV 7181R

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. SNM22D206954/C02/KHONGLH

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

06/27

Person Contacted:

Vehicle: IN / OUT

Veh No:

Pmw 9040A

Yr Regn:

06, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

c.c

1998

Colour

M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

409302

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMF026407S200093

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F/Continental 225/40R18

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

7

mm

L/Bal.

8

mm

L/Bal.

7

mm

D.O.A.

28/9/22

D.O.I.

30/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

G01 B2

Kennet confirmed lump sum: \$5200 and 6 days

(red, \$13561.44, 72%)

Date/Time, File Pass to?

1) 15/02/23

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS - SI

F. P. S.

Others

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

tp

Lump Sum / I.B.I. (\$

5200

TOTAL

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date : 29 / 09 / 2022

ESTIMATE	COSTS	OF	REPAIR
----------	-------	----	--------

Mr. Ng Jackie

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

Dear Sir / Madam ,

Vehicle no. : SGV 7181 R - Honda Civic 2.0L A

Accident date : 28 / 09 / 2022

Not Authorized

1/1 Pay @

Money After Paint

6 days

Quantity	Descriptions	Amount (S\$)
----------	--------------	----------------

1	1 pc boot lid	<i>By</i> \$ 1,090.70 ✓
2	1 pc boot lid inner lock	\$ <i>Na</i> 257.30 ✓
3	1 pc boot lid lock catch	\$ <i>R</i> 27.00 X
4	2 pcs boot lid hinge 1 @ 255.00	\$ <i>R</i> 510.00 X
5	2 pcs boot lid hinge garnish 1 @ 200.00	\$ <i>in</i> 400.00 X
6	1 pc boot lid Honda logo	\$ <i>Na</i> 101.30 ✓
7	2 pcs boot lid reflector 1 @ 184.80	\$ <i>in</i> 369.60 X
8	2 pcs boot lid no. plate lamp 1 @ 28.80	\$ <i>in</i> 57.60 X
9	1 pc boot lid no. plate lamp garnish	\$ <i>in</i> 101.30 X
10	1 pc boot lid inner trim	\$ <i>in</i> 321.00 X
11	1 pc boot lid weather strip	<i>Di 1/2</i> \$ 87.60 <i>50% in</i>
12	1 pc rear bumper fascia	\$ <i>By</i> 801.20 ✓
13	2 pcs rear bumper side retainer 1 @ 23.20	\$ <i>Di</i> 46.40 ✓
14	10 pcs rear bumper clip 1 @ 3.50	\$ <i>Na</i> 35.00 ✓
15	1 pc rear bumper lower lip	\$ <i>By</i> 850.00 ✓
16	2 pcs rear fender inner garnish 1 @ 314.00	<i>C/S ?</i> \$ <i>Di</i> 628.00
17	1 pc rear end panel	\$ <i>By</i> 289.50 ✓
18	1 pc rear end panel inner shield	\$ 145.00 ?
19	2 pcs tail lamps 1 @ 295.70	\$ <i>CM</i> 591.40 ✓
20	2 pcs tail lamp panel 1 @ 159.40	\$ <i>R</i> 318.80 X
21	1 pc rear floor panel	\$ <i>R</i> 911.40 X
22	1 pc rear exhaust box <i>PA</i>	\$ 3,500.00 ?
23	1 pc rear exhaust aluminium cover	\$ <i>R</i> 191.00 X
24	1 pc rear exhaust box center	\$ <i>R</i> 1,800.00 X
25	6 pcs rear exhaust mounting 1 @ 58.35	\$ <i>in</i> 350.10 X
26	1 pc rear windscreen glass molding	\$ <i>in</i> 83.00 X
27	1 pc rear spare tyre board	\$ 308.30 ?
28	1 pc rear spare tyre holder	\$ <i>in</i> 19.80 X
		\$ 14,192.30
Less 20 %		\$ 2,838.46
Balance C/FD		\$ 11,353.84

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Balance B/FD (SGV7181R)

\$ 11,353.84

29	1 pc	rear end panel inner garnish (carbon)
30	1 pc	rear camera
31	1 pc	rear panel seal
32	4 pcs	rear reverse sensor 1 @ 226.90
33	1 pc	rear windscreen glass inner seal
34	1 pc	rear windscreen glass inner gum

\$	350.00	sn	7
\$	Sn 450.00	sn	X
\$	na 250.00	sn	301n
\$	na 907.60	sn	2001n
\$	na 60.00	sn	X
\$	na 60.00	sn	X

\$ 13,431.44

Labour charges
To putty and spray painting
To re-seal anti rust
To check wiring, & reset fault code
Remove rear exhaust box
Remove and refix rear reverse sensor
Remove and refix rear windscreen glass
Remove and refix rear cushion seat, garnish, carpet, etc

\$	2,200.00	7001
\$	2,000.00	8001
\$	200.00	602
\$	120.00	201
\$	180.00	7
\$	120.00	601
\$	na 160.00	X
\$	350.00	801

\$ 18,761.44

\$ 1,313.30

\$ 20,074.74

Plus: 7% GST

Grand total

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	29/09/2022 13:16 (SGT)
Reported by	Both
Date of Accident	28/09/2022 17:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE TOWARDS CHANGI (NEAR EXIT 9)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGV7181R

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	NG JACKIE
NRIC No	SXXXX663D
Email Address	jackie5663@gmail.com
Mobile Phone No	(Phone) +65-93686699
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Civic
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Manual
CC	2000

INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5122207779-01

DRIVER

Name of Driver	NG JACKIE
NRIC No	SXXXX663D
Date Of Birth	07/11/1983
Occupation	Indoor

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel
(Name as in NRIC/ND card)

Sketch Plan





SINGAPORE POLICE FORCE

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20220929/7012

1 of 4

Report No. T/20220929/7012

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
29/09/2022 10:34

Vide Report No.:

Station Diary No.:

Informant's Particulars

Name of Informant:
NG JACKIE

Address:
251 COMPASSVALE STREET #11-35 SINGAPORE 540251

ID Type / ID No.:
NRIC NO / S8335663D

Contact No.:
Home/Office: Mobile: 93686699

Nationality:
SINGAPORE CITIZEN

Email:
JACKIE5663@GMAIL.COM

Sex: Male Age: 38 Date of Birth: 07/11/1983

Type of Informant:
Driver

Race:
Chinese

Language: English Institution / School Name:

Occupation:

Driving Licence Information:
Class: 3 Date of Expiry:

General Information of the Accident

Type of
Accident:

Injury
Others

Drink
Drive:
No

Date/Time of
Accident:
28/09/2022 17:30

Type of Location:
Straight Road

Location:

PIE TOWARDS CHANGI

Weather:
Clear

Road Surface:
Dry

Road Speed Limit:

Traffic Flow:
One Way

Traffic Control:
Not Controlled

Traffic Volume:
Heavy

Type of Collision:
Between Moving Vehicles - Head To Rear

Anyone conveyed by
ambulance:
No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of
SGV7181R	Car	HONDA	CIVIC 2.0L A	Blue	Seriously Damaged	0
SMW8040A	Car	HYUNDAI	CN7 AVANTE 1.6 DOHC CVT S	Black	Seriously Damaged	1



SINGAPORE POLICE FORCE

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20220929/7012

3 of 4

Report No. T/20220929/7012

CONTINUATION OF REPORT

Driver			
Name	MUHAMMAD FARHAN BIN SAEMAN		
Related Vehicle	SNE6815J (Car)	ID No.	S9305852F
Hospital/Clinic	NIL	Contact No.	96530310
Date	NIL	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
No. of Days granted Medical Leave	NIL	Date	NIL
		Degree of	NIL

Brief Details.

On 28/09/2022 at about 1730 hrs, While I was driving my motor vehicle A (SGV7181R) along PIE heading to Changi direction at the extreme right lane. When I almost reached near to PIE Exit9. Keeping within my lane, suddenly the vehicles in front of me jam brake and I managed to stopped in time but the vehicle B (SMW9040A) which was driving behind of me, can not stopped in time and hit onto the rear portion of my stationary vehicle A. Afterward, I realised that had another vehicle C (SNE6815J) hit onto the rear portion of vehicle B (SMW9040A). I go for medical checkup and have 3 days MC from the Doctor. I'm lodging this report to claim again the insurer of SMW9040A.