

REC BY: TEUFAN REF: CS/ASM 22009701/Tay3 Tqy3

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated cost: \_\_\_\_\_  
OD (TP / VS / TPRES / OD RES / EVA / INV / MV)  
To inspect Vehicle No: \_\_\_\_\_  
at Workshop this \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No: \_\_\_\_\_  
Claims Nil \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

N/S	O/S
	X

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.  
Bal. or Market Value: \$800K  
IDAC Accident Rpt \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 8 days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS W' PRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMN2922Z Yr Regn: 2019, July  
Type: MCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: Hyundai Avante C.C. 1511  
Colour: White A/C: Insured / Std / Nil / NA  
Sp. Reading: 240247 T/Radio: Insured / Std / Nil / NA  
Eng/No: \_\_\_\_\_  
C/No: KM H1D841 CMK-4934029  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Modi: Nil / 3 Rim / STD A/Rim or \_\_\_\_\_  
Tyre Size: F: 195/65R15  
R: 195/65R15  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /  
TOYO / YOKO, etc Kapsen  
Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. \_\_\_\_\_ D.O.I. 3/10/220249  
Survey held at D's Graffiti  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair Range: \$7000-8800, 8 days</u>
	<u>17/01/23 submit prs / repair range: \$7k-\$8k and 8 days</u>

Date/Time, File Pass to? ☐ : Prel. Report  
1) 17/01/23 ☐ : Final Report  
Date/Time, File Return to?

Days Of Repair: 8  
Resurvey No. of Trip: 1

2) \_\_\_\_\_  
Report Format: prs  
Lump Sum / L&L: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Insp (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
S + RS	SI
Photos	
Others	