

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	198R GST Reg. No. 19-9	9607198-R	
		Affiliated to Federation Internation	nale Des Experts En Aut	omobile	
	AUTO & GENERA	L INSURANCE (S) PL	Ref	f: CS/AGI22009723/Uny3e2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Dai	te: 11/10/2022	
			Co	de: AGI	
1.		Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SFH 7880S	Veh. Inspected	SCR 136L	
	Policy No.	P10712468R00	Coverage (\$)	0.00	
	Claim No.	C10017820/CH	Excess (\$)	0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date	03/10/2022	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA AIRWAVE (A)	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	GJ11304182	Colour	BLUE	
	Odometer	275892 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/55 R15	WEST LAKE	6 mm	
	L/H Front Tyre	195/55 R15	WEST LAKE	6 mm	
	R/H Rear Tyre	195/55 R15	WEST LAKE	6 mm	
	L/H Rear Tyre	195/55 R15	WEST LAKE	6 mm	
4.	Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	29/09/2022	Inspection Date	04/10/2022	
	Survey held at JIN AUTO SERVICES PTE LTD				
		BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195			
5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	DJIN ACCORDANC	Estimate Days of Repair			
	Louinate Days of Nepall				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: