



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                        |                                                                                                                                        |                                                                          |                                                           |            |
|----------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|-----------------------------------------------------------|------------|
| TOKIO MARINE INSURANCE SINGAPORE LTD<br>20 MCCALLUM STREET #09-01<br>TOKIO MARINE CENTRESINGAPORE 069046 |                                                                                                                                        |                                                                          | Ref: CS/TMI22009748/Tny3<br>Date: 04/10/2022<br>Code: TMI |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                        |                                                                                                                                        |                                                                          |                                                           |            |
|                                                                                                          | Insured Veh.                                                                                                                           | SLE 7193L                                                                | Veh. Inspected                                            | SHA 3812D  |
|                                                                                                          | Policy No.                                                                                                                             | MN000293                                                                 | Coverage (\$)                                             | 0.00       |
|                                                                                                          | Claim No.                                                                                                                              | M2205435                                                                 | Excess (\$)                                               | 0.00       |
|                                                                                                          | Assign From                                                                                                                            | YEE PEI LI                                                               | Assign Date                                               | 04/10/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                            |                                                                                                                                        |                                                                          |                                                           |            |
|                                                                                                          | Make & Model                                                                                                                           |                                                                          | c.c                                                       | 0          |
|                                                                                                          | Engine No.                                                                                                                             | HIDDEN                                                                   | Year of Reg.                                              |            |
|                                                                                                          | Chassis No.                                                                                                                            |                                                                          | Colour                                                    |            |
|                                                                                                          | Odometer                                                                                                                               | -                                                                        | Steering                                                  |            |
|                                                                                                          | Brakes                                                                                                                                 |                                                                          | Modification                                              |            |
|                                                                                                          | General                                                                                                                                |                                                                          |                                                           |            |
| <b>3. Conditions of Tyres</b>                                                                            |                                                                                                                                        |                                                                          |                                                           |            |
|                                                                                                          |                                                                                                                                        | Size                                                                     | Make                                                      | Balance    |
|                                                                                                          | R/H Front Tyre                                                                                                                         |                                                                          |                                                           | mm         |
|                                                                                                          | L/H Front Tyre                                                                                                                         |                                                                          |                                                           | mm         |
|                                                                                                          | R/H Rear Tyre                                                                                                                          |                                                                          |                                                           | mm         |
|                                                                                                          | L/H Rear Tyre                                                                                                                          |                                                                          |                                                           | mm         |
| <b>4. Description of Damages</b>                                                                         |                                                                                                                                        |                                                                          |                                                           |            |
|                                                                                                          |                                                                                                                                        |                                                                          |                                                           |            |
| <b>5. General Information</b>                                                                            |                                                                                                                                        |                                                                          |                                                           |            |
|                                                                                                          | Accident Date                                                                                                                          | 02/10/2022                                                               | Inspection Date                                           | 04/10/2022 |
|                                                                                                          | Survey held at                                                                                                                         | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                                                           |            |
| <b>5a. Remarks</b>                                                                                       |                                                                                                                                        |                                                                          |                                                           |            |
|                                                                                                          | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                          |                                                           |            |