

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

EQ Insurance Company Ltd (HQ)

Loke Wei Yiang

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	03/10/2022
Vehicle Reg. No.:	SHB6253S	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	03/07/2018
Vehicle Colour:	BLUE	Chassis No:	KMHC851CVJU103381
Engine No:	G4LEJU045572		
Odometer:	437921 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,435.56
Miscellaneous Items	0.00
Labour	980.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,415.56
+ GST 7.00% (S\$)	169.09
Nett Amount (S\$)	2,584.65

This claim is handled by: MS. LOKE YY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Oct 2022)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHB6253S/03/10/2022 14:20

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	20.00	0.00	Rp *459.40 FL
2	1		*REAR BUMPER CLIPS	20.00	0.00	ne *22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	20.00	0.00	dl *451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	? *394.80 FL
5	1		*ANTENNA SMARTKEY	20.00	0.00	X *40.50 FL
6	1		*REAR BUMPER FOG LAMP	20.00	0.00	X *201.50 FL
7	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00	nu *180.00 F
				Sub Total (\$\$)		1,749.45
				- List Item Discount on L Items (\$\$)		313.89
				Total Parts (\$\$)		1,435.56

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHB6253S/03/10/2022 14:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

473.25
20% 378.60
511.80

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	RENEW ADVERTISEMENT STICKER LH RH	New	200.00
2	PANEL BEATING	New	400.00
3	SPRAY PAINTING CHARGE	New	300.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00
Gross Labour Cost (S\$)			980.00

ComfortDelGro Engineering Pte Ltd/SHB6253S/03/10/2022 14:20. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 9240 5749
 WP' 4/10/22 @ 21.5pm
 = 2 days
 L/S Resurvey after repair
 Tanpin @/shantou

378.60
 180
 830

 1388.60
 458/1100
 = 2 days
 #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4944656

JC No: 805532076

CUSTOMER
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
TEL (R) 65508755 (O)
(P)
SCOUT CARD NO.


REGN NO: SHB6253S	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 03.10.2022 11:10
YR OF MANU. 03.07.2018	TARGET DATE
CHASSIS CODE KMHC851CVJU103381	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 03.10.2022
NATURE: 3P 03.10.2022

S/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledge Slip

Exit Pass

Name:
No.:
Vehicle No.: **SHB6253S** YY

Vehicle No.: **SHB6253S**

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be returned to Service Reception upon collection

To be kept by Security Guard