





*NOT Adhered  
L1 By B  
Murray Alex Paim*

### Case Details

Case Reference Number : TAX/09/22/2083  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHD6117S

Company Type : Strides Taxi Pte Ltd  
 Estimation ID : EST-19464-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : income insurance limited  
 Accident Date and Time : 28/09/2022 07:55 AM  
 Vehicle Age(In Months) : -

### Documents / Photographs

[View Documents / Photographs](#) Total Documents: 0

### Estimation Details

#### Spare Part's Cost Detail

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation	List Price Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
						Surveyor Approval									
Standard	Main			COVER, FR BUMPER	1		565.60	565.60	25.00	424.20	Replace	1	424.2	Replace	<i>Buc</i>
Standard	Main			SUPPORT, FR BUMPER LH	1		86.20	86.20	25.00	64.65	Replace	1	64.65	Replace	<i>Dit</i>
Standard	Main			COVER, FR BUMPER LH	1		32.70	32.70	25.00	24.53	Replace	1	24.53	Replace	<i>Mit</i>
Standard	Main			SEAL, HOOD TO FR END	1		92.40	92.40	25.00	69.30	Replace	0	0	Not Give	
Standard	Main			GRILLE, RADIATOR	1		192.80	192.80	25.00	144.60	Replace	0	0	Not Give	
Standard	Main			GRILLE SUB-ASSY	1		457.10	457.10	25.00	342.83	Replace	0	0	Not Give	
Standard	Main			GRILLE, SUB - ASSY , 2	1		170.20	170.20	25.00	127.65	Replace	0	0	Not Give	
Standard	Main			COVER ASSY, ENGINE	1		261.60	261.60	25.00	196.20	Replace	0	0	Not Give	
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10		4.80	48.00	25.00	36.00	Replace	10	36.00	Replace	<i>Mu</i>
Standard	Main			RETAINER, FR BUMPER, LH & RH	1		9.50	9.50	25.00	7.13	Replace	0	0	Not Give	
Standard	Main			PAD, FRONT BUMPER ( NO.1)	1		44.10	44.10	25.00	33.08	Replace	0	0	Check	
Standard	Main			PAD, FRONT BUMPER ( NO.2)	1		38.90	38.90	25.00	29.17	Replace	0	0	Check	
Standard	Main			MOULDING, FRONT BUMPER SIDE, LH	1		103.70	103.70	25.00	77.78	Replace	1	77.78	Replace	<i>GRA</i>
Standard	Main			ABSORBER, FR BUMPER LOWER	1		143.60	143.60	25.00	107.70	Replace	0	0	Check	

Total Spare Part Cost	11,002.26	Surveyor Total	3,412.13
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20.00
Final Spare Part Cost	8,801.81	Final Sur Total	2,729.70

9/22, 3:00 PM

S.No. Costing Ty

2 Main

3 Main

4 Main

Total:

Other Cos

S.No. C

1

2

3

4

T

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			ABSORBER, FR BUMPER	1	86.60	86.60	25.00	64.95	Replace	0	0	Check	
Standard	Main			REINFORCEMENT FRONT LOWER	1	265.90	265.90	25.00	199.42	Replace	0	0	Not Give	
Standard	Main			REINFORCEMENT FRONT UPPER	1	773.90	773.90	25.00	580.43	Replace	0	0	Not Give	
Standard	Main			UNIT, HEADLAMP, LH	1	2,852.40	2,852.40	10.00	2,567.16	Replace	1	2,567	Replace	W
Standard	Main			COMPUTER SUB-ASSY, HEADLAMP, LH	1	4,079.80	4,079.80	10.00	3,671.82	Replace	0	0	Not Give	
Standard	Main			LAMP ASSY, FOG LH	1	236.50	236.50	10.00	230.85	Replace	0	0	Check	
Standard	Main			COVER, ENGINE UNDER SIDE LH	1	86.20	86.20	25.00	64.65	Replace	0	0	Not Give	
Standard	Main			HOOD SUB-ASSY	1	1,066.30	1,066.30	25.00	799.72	Replace	0	0	Not Give	
Standard	Main			FENDER SUB-ASSY, FR, LH	1	1,060.70	1,060.70	25.00	795.53	Replace	1	0	Repair	
Standard	Main			EMBLEM, SIDE PANEL (HYBRID)	1	59.10	59.10	25.00	44.33	Replace	1	44.33	Replace	Mei
Standard	Main			LINER, FR FENDER, LH	1	227.80	227.80	25.00	170.85	Replace	1	170.8	Replace	CM
Standard	Main			RETAINER, FR WHEEL RH	1	3.50	3.50	25.00	2.63	Replace	1	2.63	Replace	Mei
Standard	Main			PROTECTOR, FR FENDER LH	1	101.80	101.80	25.00	76.35	Replace	0	0	Not Give	
Standard	Main			PAD, FR WHEEL LH	1	65.00	65.00	25.00	48.75	Replace	0	0	Not Give	
Total Spare Part Cost									11,002.26	Surveyor Total		3,412.13		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20.00		
Final Spare Part Cost									8,801.81	Final Sur Total		2,729.70		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	845.00	300.00	
Total:			845.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200.00	
Total:			1,314.00	400.00	

9/30/22, 3:00 PM

https://vacweb.smr.com.sg/Estimation.aspx

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO RESPRAY FRONT HOOD	378.00	0	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
4	Main	TO RESPRAY FRONT FENDER LH	378.00	200.00	
<b>Total:</b>			<b>1,314.00</b>	<b>400.00</b>	

**Other Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	20.00	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	
<b>Total:</b>			<b>380.00</b>	<b>20.00</b>	

**Summary**

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	8,801.81	2,729.70
Total Labour Cost	845.00	300.00
Total Spray Painting	1,314.00	400.00
Other	380.00	20.00
<b>Overall Total</b>	<b>11,340.81</b>	<b>3,449.70</b>
Lump Sum Repair Option	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	11,350.00	3,450.00
Surveyor Approved Amount		3,450.00
No of Repair Days*	6	3
Remarks	-	Lump sum repair / resurvey after paint / after paint photos / FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP: 9594 9552
Surveyor Name		Kenneth Kong (LKK)

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	30/09/2022 14:14 (SGT)
Reported by	Driver
Date of Accident	28/09/2022 15:55 (SGT)
Exact Location of Accident	70 Airport Blvd., Changi Airport, Singapore 819661
Additional Location Information	CHANGI AIRPORT T2 ARRIVAL HALL PICK UP
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD6117S

### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

### INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-22099115MFSH

### DRIVER

Name of Driver	TAN YEW LING
NRIC No	SXXXX118B
Date Of Birth	02/04/1959
Occupation	Outdoor

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims,
- (ii) investigating the accident and/or my claims,
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers, lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

*[Handwritten Signature]*

Driver's Signature (if driver is not the policyholder) / Date & Time

*[Handwritten Signature]*

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan

