



# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No.2 Pandan Crescent  
Singapore 128462, Tel no.: 6631 1388



## ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233  Mobile: 96889560
	Document No. 0	
	Document Date 03/10/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHB11B1802003118	A25A0237541	60	Wally Tan G H	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMPCSNW00161062200 ACC DATE:02.10.2022 TOW/DRIVE IN: EXCESS: DATE-IN:03.10.2022 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				80.00
2	B	BP-LAB3 TRANSFER BOOT LID COMPONENT AND MECHANISM TO NEW DOOR SHELL. (NETT)				433.00
3	B	BP-LAB3 REMOVE/REFIX REVERSE CAMERA. (NETT)				216.50
4	B	BP-LAB3 REMOVE/REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR. (NETT)				433.00
5	B	BP-LAB3 CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE.(NETT)				216.50
6	B	BP-LAB3 REMOVE/REFIX REVERSE SENSORS. (NETT)				216.50
7	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN REAR PANEL, SPARE WHEEL PAN, R/R AND L/R BODY PANELS, CUT AND WELD PANEL AND FIT NEW PARTS.				4330.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less  Amount Due

Customer Copy



# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No.2 Pandan Crescent  
Singapore 128462, Tel no.: 6631 1388



## ESTIMATE

<b>Account Details</b>		<b>Account No.</b>	<b>Customer Details</b>	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233  Mobile: 96889560	
		<b>Document No.</b>		
		0		
		<b>Document Date</b>		
		03/10/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHB11B1802003118	A25A0237541	60	Wally Tan G H	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
8	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				4081.00
9	Z	BP-SLANT SUPPLY SEALANT (NETT) BOOT AND REAR PANEL				200.00
10	B	BP-MECH3 TO RESET ECU AND REPROGRAMME. (NETT)				216.50
11	1	L64401-33860 PANEL SUB-ASSY,	1.00	902.00		902.00
12	2	L64510-33271 HINGE ASSY, LUGGAGE	1.00	242.40		242.40
13	3	L64520-33131 HINGE ASSY, LUGGAGE	1.00	229.10		229.10
14	4	L64719-33300 C0 COVER, LUGGAGE	1.00	543.90		543.90
15	5	T90467-08186 C3 CLIP	14.00	2.70		37.80
16	6	L64713-33070 COVER, LUGGAGE	1.00	102.90		102.90
17	7	L64714-33060 COVER, LUGGAGE	1.00	102.90		102.90
18	8	L64650-33040 CLOSER ASSY, LUGGAGE	1.00	1394.60		1394.60
19	9	L64461-33130 WEATHERSTRIP,	1.00	272.70		272.70
20	0	L76801-33721 GARNISH SUB-ASSY,	1.00	604.70		604.70
21	1	T81204-47010 LAMP SUB-ASSY,	1.00	311.50		311.50
22	2	L90975-02154 EMBLEM, SYMBOL	1.00	77.30		77.30
23	3	L75447-33200 PLATE, LUGGAGE COMPT	1.00	73.80		73.80
24	4	L75442-33500 PLATE, LUGGAGE COMPT	1.00	73.80		73.80
25	5	L81580-33471 LAMP ASSY, RR, RH	1.00	1149.20		1149.20

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less  Amount Due

Customer Copy



# Borneo Motors

Inchocpe

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No.2 Pandan Crescent  
Singapore 128462, Tel no.: 6631 1388



## ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233  Mobile: 96889560
	Document No. 0	
	Document Date 03/10/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHB11B1802003118	A25A0237541	60	Wally Tan G H	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
26	6	L81590-33472 LAMP ASSY, RR, LH	1.00	1149.20		1149.20
27	7	L76817-26040 CLIP,	2.00	3.90		7.80
28	8	L52157-33040 SUPPORT, RR BUMPER	1.00	147.30		147.30
29	9	L52158-33040 SUPPORT, RR BUMPER	1.00	147.30		147.30
30	0	L52585-33010 INSERT, RR BUMPER	1.00	27.20		27.20
31	1	L52586-33010 INSERT, RR BUMPER	1.00	27.20		27.20
32	2	L52581-33010 PROTECTOR, RR	1.00	200.30		200.30
33	3	L52582-33010 PROTECTOR, RR	1.00	201.90		201.90
34	4	L52171-33170 REINFORCEMENT, RR	1.00	802.50		802.50
35	5	L52615-33210 ABSORBER, RR BUMPER	1.00	120.90		120.90
36	6	L52155-33020 SUPPORT, RR BUMPER	1.00	85.00		85.00
37	7	L52156-33020 SUPPORT, RR BUMPER	1.00	92.80		92.80
38	8	L52567-33040 RETAINER, RR BUMPER	1.00	149.70		149.70
39	9	L52159-33979 COVER, RR BUMPER	1.00	1403.40		1403.40
40	0	L75895-78030 TAPE, MOULDING, NO.1	2.00	43.00		86.00
41	1	L52105-33020 BUMPER SUB-ASSY, RR	1.00	732.40		732.40
42	2	L891B1-33020 BRACKET, KICK DOOR	1.00	155.20		155.20
43	3	L891B2-06021 SENSOR, KICK DOOR	1.00	749.30		749.30
44	4	S52161-0K040 PIECE, RR BUMPER	17.00	4.50		76.50
45	5	L89348-50130 RETAINER, ULTRASONIC	4.00	19.20		76.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No.2 Pandan Crescent  
 Singapore 128462, Tel no.: 6631 1388



## ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233  Mobile: 96889560
	Document No. 0	
	Document Date 03/10/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHB11B1802003118	A25A0237541	60	Wally Tan G H	--/--	0.00 --/--

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
46	6	L89348-58130 CLIP, ULTRASONIC	4.00	12.90		51.60
47	7	L89341-33220 GO SENSOR, ULTRASONIC,	4.00	491.40		1965.60
48	8	L81910-33040 REFLECTOR ASSY,	1.00	52.80		52.80
49	9	L81920-33030 REFLECTOR ASSY,	1.00	52.80		52.80
50	0	L82182-33240 WIRE, LUGGAGE ROOM,	1.00	192.10		192.10
51	1	L88162-33102 SENSOR, BLIND SPOT	2.00	2163.70		4327.40
52	2	L88163-33040 COVER, BLIND SPOT	1.00	97.40		97.40
53	3	L88173-33040 COVER, BLIND SPOT	1.00	97.40		97.40
54	4	L81550-33592 LAMP ASSY, RR	1.00	1476.70		1476.70
55	5	L81560-33592 LAMP ASSY, RR	1.00	1476.70		1476.70
56	6	L81497-33030 COVER, RR	1.00	40.60		40.60
57	7	L81498-33030 COVER, RR	1.00	40.60		40.60
58	8	T81496-60010 GUIDE, RR	2.00	3.90		7.80
59	9	L81496-52020 GUIDE, RR	2.00	2.80		5.60
60	0	L52562-33070 RETAINER, RR BUMPER,	1.00	65.00		65.00
61	1	L52563-33050 RETAINER, RR BUMPER,	1.00	65.00		65.00
62	2	L51931-53050 CARRIER, SPARE WHEEL	1.00	28.10		28.10
63	3	L64779-33290 TRAY, SPARE WHEEL	1.00	280.50		280.50
64	4	L64711-33300 C0 MAT, LUGGAGE	1.00	777.60		777.60
65	5	L64429-33030 BOX, LUGGAGE	1.00	763.60		763.60

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No.2 Pandan Crescent  
Singapore 128462, Tel no.: 6631 1388



## ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233  Mobile: 96889560
	Document No. 0	
	Document Date 03/10/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHB11B1802003118	A25A0237541	60	Wally Tan G H	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
66	6	L58387-33160 CO PLATE, RR FLOOR	1.00	389.60		389.60
67	7	L58307-33191 PANEL SUB-ASSY, BODY	1.00	908.50		908.50
68	8	L89997-30100 ANTENNA, ELECTRICAL	1.00	78.00		78.00
69	9	L58747-33090 PROTECTOR, QUARTER	1.00	30.90		30.90
70	0	L58748-33100 PROTECTOR, QUARTER	1.00	30.90		30.90
71	1	L67857-33080 PROTECTOR, RR DOOR	1.00	25.30		25.30
72	2	L67858-33080 PROTECTOR, RR DOOR	1.00	25.30		25.30
73	3	L57628-33130 COVER, RR FLOOR SIDE	1.00	420.80		420.80

For & on behalf of	Customer's Signature	Charge Summary	Total	36,754.50
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle  	Parts	26,331.50	GST 7.00% 2,572.82 Less 0.00 Amount Due 39,327.32
		Labour	10,423.00	
		Sublet	0.00	
		Lubrication/Fluid	0.00	
		Others	0.00	

Customer Copy

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	03/10/2022 14:01 (SGT)
Reported by	Both
Date of Accident	02/10/2022 21:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE TOWARDS CHANGI NEAR STEVEN ROAD EXIT
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGC8108Y
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	ONG CHU KIAT
NRIC No	SXXXX144H
Email Address	AOCK99@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-96889560
Alternative Phone No	-

## VEHICLE PARTICULARS

Manufacturer	Lexus
Model	Es250
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2500

## INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMPCSNW00161062200

## DRIVER

Name of Driver	ONG CHU KIAT
NRIC No	SXXXX144H
Date Of Birth	06/10/1975
Occupation	Outdoor

Date Of Driving Pass	10/12/1998
Driving experience	23 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96889560
Alt. Phone Number	-
Email Address	AOCK99@YAHOO.COM.SG
Address	BLK 233 BISHAN ST 22 #04-132
Address complement	-
Postcode	570233
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	5
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	LEE YING LIN
Gender	Female

PASSENGER 2

Name	ONG KAI XUAN
Gender	Male

PASSENGER 3

Name	ONG ZHI XUAN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
---	-----

Was there any video captured by Car Camera?

No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMY5384Z
Vehicle Manufacturer	Mercedes
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	JEREMY WONG CHUN KIT
NRIC No	SXXXX166J
Contact Number	(Phone) +65-93803391
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHB9779Y
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	-
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	-
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-

Vehicle Category	NA / Unknown
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person	-
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	-
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

**SKETCH PLAN**

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to renege on policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


**5 Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

  
 Policyholder's Signature / Date & Time  
 03/10/22  
 Sketch Plan
 

  
 Driver's Signature (if driver is not the policyholder) / Date & Time
 

  
 Witnessed by Reporting Centre Personnel  
 (Name as in NRIC/ID card)



**Describe Circumstance of the Accident**

At around 9pm, I was travelling along PIE towards Changi direction near Steven Rd exit at 90 km/h. Suddenly at around 200m away, I saw some vehicles stopped at Lane 1 of the highway and I applied brake to slow down.

I managed to stop in front of the stalled vehicles (actually there was another accident). I waited for about 5 sec before trying to ~~shift~~ filter to Lane 2 so that I can overtake the stalled vehicles. However before I can filter out, I heard a loud ~~sound~~ <sup>boom</sup> behind my vehicle and followed by another loud sound and felt my vehicle surged forward.

I quickly pressed the hazard light & and alighted to check what happened. I saw a merc A180, smy538VZ hit onto the rear of my vehicle.

**Declaration**

I/We declare the foregoing particulars are true in every respect

\_\_\_\_\_  
Policyholder's Signature / Date & Time

\_\_\_\_\_  
Driver's Signature (if driver is not the policyholder) / Date & Time

\_\_\_\_\_  
Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)