

ASSIGNMENT

ASS REC BY: Steve

CS/CT122009774/EM3

ASSIGNMENT

From: _____ Date: _____

Veh No: SGC 8108Y Yr Regn: 31/12/18

Estimated Cost: _____

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: _____

Make: LEXUS LS750 c.c. 7494

at Workshop m/s _____

Colour: Green A/C: Insured / Std / NI / NA

of _____

Sb. Reading 30134 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. DMPCSNW00161062200

C/No: JTHB/1181807003/18

Claims No. SNM22D207021/C01/TANKL

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: 1000

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: _____

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/45R18

R: _____

(Policy Condition)

N/S	O/S
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Bal. or Market Value: _____

Front R/Bal. 5 mm Rear R/Bal. 5 mm

IDAC Accident Report: _____ Consistent? : Yes or No

L/Bal. 5 mm U/Bal. 5 mm

GIA / PR Seen: _____ Consistent? : Yes or No

D.O.A. 2/10/22 D.O.I. 4/10/22

Est. Repairs: _____ days Res.: Yes or No

Survey held at Borneo

Lum Sum: _____ % 3 Val.: Yes or No

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

CA / REV / REP. / 24 HRS

The UIC / Chassis frame / Body Structure affected due to collision.

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>MV-147K</u>
<u>3/11/22</u>	<u>Steve informed final fig \$20,774.90 (Red 16,075.60, 43%)</u>

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: 14

: Final Report

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Date/Time, File Return to?

1) _____

Report Format: Merimen

Lump Sum / L.S.J. (\$ \$20,774.90)

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech, Invs (\$ _____)

: Weekend (\$ _____)

S + RS. \$ _____

Photos

Others

TOTAL



Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 Pandan Crescent
Singapore 128462, Tel no: 6631 1388

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233 Mobile: 96889560
	Document No. 0	
	Document Date 03/10/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHB11B1802003118	A25A0237541	60	Wally Tan G H	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMPCSNW00161062200 ACC DATE:02.10.2022 TOW/DRIVE IN: EXCESS: DATE-IN:03.10.2022 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 80.00
2	B	BP-LAB3 TRANSFER BOOT LID COMPONENT AND MECHANISM TO NEW DOOR SHELL. (NETT)				433.00 ✓
3	B	BP-LAB3 REMOVE/REFIX REVERSE CAMERA. (NETT)				216.50 ✓
4	B	BP-LAB3 REMOVE/REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR. (NETT)				433.00 ✓
5	B	BP-LAB3 CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE.(NETT)				216.50 ✓
6	B	BP-LAB3 REMOVE/REFIX REVERSE SENSORS. (NETT)				216.50 ✓
7	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN REAR PANEL, SPARE WHEEL PAN, R/R AND L/R BODY PANELS, CUT AND WELD PANEL AND FIT NEW PARTS. <i>5 x 866</i>				4330.00 ✓

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233 Mobile: 96889560
	Document No. 0	
	Document Date 03/10/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHB11B1802003118	A25A0237541	60	Wally Tan G H	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
8	B	BP-RES3 SPRAY PAINT ON DAMAGED 742 x 5 AFFECTED PORTION OF CAR.				3710 4081.00
9	Z	BP-SLANT SUPPLY SEALANT (NETT) BOOT AND REAR PANEL				200.00
10	B	BP-MECH3 TO RESET ECU AND REPROGRAMME. (NETT)				216.50
11	1	L64401-33860 PANEL SUB-ASSY, / <i>OD</i>	1.00	902.00		902.00
12	2	L64510-33271 HINGE ASSY, LUGGAGE	1.00	242.40		242.40
13	3	L64520-33131 HINGE ASSY, LUGGAGE	1.00	229.10		229.10
14	4	L64719-33300 C0 COVER, LUGGAGE	1.00	543.90		543.90
15	5	T90467-08186 C3 CLIP / <i>nc</i>	14.00	2.70		37.80
16	6	L64713-33070 COVER, LUGGAGE / <i>nc</i> { @ full trim }	1.00	102.90		102.90
17	7	L64714-33060 COVER, LUGGAGE / <i>nc</i>	1.00	102.90		102.90
18	8	L64650-33040 CLOSER ASSY, LUGGAGE / <i>OT</i>	1.00	1394.60		1394.60
19	9	L64461-33130 WEATHERSTRIP, / <i>CRM</i>	1.00	272.70		272.70
20	0	L76801-33721 GARNISH SUB-ASSY, / <i>nc</i>	1.00	604.70		604.70
21	1	T81204-47010 LAMP SUB-ASSY, / <i>nc</i>	1.00	311.50		311.50
22	2	L90975-02154 EMBLEM, SYMBOL / <i>nc</i>	1.00	77.30		77.30
23	3	L75447-33200 PLATE, LUGGAGE COMPT / <i>nc</i>	1.00	73.80		73.80
24	4	L75442-33500 PLATE, LUGGAGE COMPT / <i>nc</i>	1.00	73.80		73.80
25	5	L81580-33471 LAMP ASSY, RR, RH / <i>nc</i>	1.00	1149.20		1149.20

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 Pandan Crescent
Singapore 128462. Tel no.: 6631 1388

ESTIMATE

Account Details		Account No.	Customer Details							
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Ong Chu Kiat							
		Document No. 0	233 Bishan Street 22 #04-132 Singapore 570233							
		Document Date 03/10/2022	Mobile: 96889560							
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks			
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022			
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On					
JTHB11B1802003118	A25A0237541	60	Wally Tan G H	--/--/----	0.00	--/--/----	0.00			
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount	
26	6	L81590-33472	LAMP ASSY, RR, LH				1.00	1149.20		1149.20
27	7	L76817-26040	CLIP, <i>ne</i>				2.00	3.90		7.80
28	8	L52157-33040	SUPPORT, RR BUMPER				1.00	147.30		147.30
29	9	L52158-33040	SUPPORT, RR BUMPER				1.00	147.30		147.30
30	0	L52585-33010	INSERT, RR BUMPER <i>mc</i>				1.00	27.20		27.20
31	1	L52586-33010	INSERT, RR BUMPER <i>mc</i>				1.00	27.20		27.20
32	2	L52581-33010	PROTECTOR, RR <i>ne</i>				1.00	200.30		200.30
33	3	L52582-33010	PROTECTOR, RR <i>ne</i>				1.00	201.90		201.90
34	4	L52171-33170	REINFORCEMENT, RR				1.00	802.50		802.50
35	5	L52615-33210	ABSORBER, RR BUMPER				1.00	120.90		120.90
36	6	L52155-33020	SUPPORT, RR BUMPER				1.00	85.00		85.00
37	7	L52156-33020	SUPPORT, RR BUMPER				1.00	92.80		92.80
38	8	L52567-33040	RETAINER, RR BUMPER				1.00	149.70		149.70
39	9	L52159-33979	COVER, RR BUMPER <i>BR</i>				1.00	1403.40		1403.40
40	0	L75895-78030	TAPE, MOULDING, NO.1				2.00	43.00		86.00
41	1	L52105-33020	BUMPER SUB-ASSY, RR <i>BR</i>				1.00	732.40		732.40
42	2	L891B1-33020	BRACKET, KICK DOOR				1.00	155.20		155.20
43	3	L891B2-06021	SENSOR, KICK DOOR				1.00	749.30		749.30
44	4	S52161-0K040	PIECE, RR BUMPER <i>ne</i>				17.00	4.50		76.50
45	5	L89348-50130	RETAINER, ULTRASONIC <i>ne</i>				4.00	19.20		76.80
For & on behalf of		Customer's Signature	Charge Summary			Total				
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts			Less				
			Labour							
		Sublet			Amount Due					
		Lubrication/Fluid								
		Others								

Customer Copy



Borneo Motors



incapex
 Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No.2 Pandan Crescent
 Singapore 128462, Tel no. : 6631 1388

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233 Mobile: 96889560
	Document No. 0	
	Document Date 03/10/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTHB11B1802003118	A25A0237541	60	Wally Tan G H	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
46	6	L89348-58130 CLIP, ULTRASONIC <i>nc</i>	4.00	12.90		51.60
47	7	L89341-33220 G0 SENSOR, ULTRASONIC, <i>nc</i>	4.00	491.40		1965.60
48	8	L81910-33040 REFLECTOR ASSY, <i>nc</i>	1.00	52.80		52.80
49	9	L81920-33030 REFLECTOR ASSY, <i>nc</i>	1.00	52.80		52.80
50	0	L82182-33240 WIRE, LUGGAGE ROOM, <i>nc</i>	1.00	192.10		192.10
51	1	L88162-33102 SENSOR, BLIND SPOT <i>nc</i>	2.00	2163.70		4327.40
52	2	L88163-33040 COVER, BLIND SPOT <i>nc</i>	1.00	97.40		97.40
53	3	L88173-33040 COVER, BLIND SPOT <i>nc</i>	1.00	97.40		97.40
54	4	L81550-33592 LAMP ASSY, RR <i>nc (RH)</i>	1.00	1476.70		1476.70
55	5	L81560-33592 LAMP ASSY, RR <i>nc (LH)</i>	1.00	1476.70		1476.70
56	6	L81497-33030 COVER, RR <i>nc</i>	1.00	40.60		40.60
57	7	L81498-33030 COVER, RR <i>nc</i>	1.00	40.60		40.60
58	8	T81496-60010 GUIDE, RR <i>nc</i>	2.00	3.90		7.80
59	9	L81496-52020 GUIDE, RR <i>nc</i>	2.00	2.80		5.60
60	0	L52562-33070 RETAINER, RR BUMPER, <i>nc</i>	1.00	65.00		65.00
61	1	L52563-33050 RETAINER, RR BUMPER, <i>nc</i>	1.00	65.00		65.00
62	2	L51931-53050 CARRIER, SPARE WHEEL <i>nc</i>	1.00	28.10		28.10
63	3	L64779-33290 TRAY, SPARE WHEEL <i>nc</i>	1.00	280.50		280.50
64	4	L64711-33300 C0 MAT, LUGGAGE <i>nc</i>	1.00	777.60		777.60
65	5	L64429-33030 BOX, LUGGAGE <i>nc</i>	1.00	763.60		763.60

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

inciscape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233 Mobile: 96889560	
		Document No. 0		
		Document Date 03/10/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHB11B1802003118	A25A0237541	60	Wally Tan G H	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
66	6	L58387-33160 C0 PLATE, RR FLOOR <i>CR4</i>	1.00	389.60		389.60
67	7	L58307-33191 PANEL SUB-ASSY, BODY <i>OD</i>	1.00	908.50		908.50
68	8	L89997-30100 ANTENNA, ELECTRICAL	1.00	78.00		78.00
69	9	L58747-33090 PROTECTOR, QUARTER <i>AK</i>	1.00	30.90		30.90
70	0	L58748-33100 PROTECTOR, QUARTER <i>AK</i>	1.00	30.90		30.90
71	1	L67857-33080 PROTECTOR, RR DOOR <i>AK</i>	1.00	25.30		25.30
72	2	L67858-33080 PROTECTOR, RR DOOR <i>AK</i>	1.00	25.30		25.30
73	3	L57628-33130 COVER, RR FLOOR SIDE <i>?</i>	1.00	420.80		420.80

*Steve (LKK)
4/10/22, 3:07pm*

*OD - L1 11L
13 days
EXA - ?
P/P
by BL Y*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Part prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
No legal indemnification is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: *[Signature]*
Date: *[Date]*

Customer's Signature	Charge Summary	Total
<i>[Signature]</i>	Parts	26,331.50
	Labour	10,423.00
	Sublet	0.00
	Lubrication/Fluid	0.00
	Others	0.00
		36,754.50
		GST 7.00%
		2,572.82
		Less
		0.00
		Amount Due
		39,327.32

Customer Copy

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	03/10/2022 14:01 (SGT)
Reported by	Both
Date of Accident	02/10/2022 21:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE TOWARDS CHANGI NEAR STEVEN ROAD EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGC8108Y

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ONG CHU KIAT
NRIC No	SXXXX144H
Email Address	AOCK99@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-96889560
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Lexus
Model	Es250
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2500

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMPCSNW00161062200

DRIVER

Name of Driver	ONG CHU KIAT
NRIC No	SXXXX144H
Date Of Birth	06/10/1975
Occupation	Outdoor

Date Of Driving Pass	10/12/1998
Driving experience	23 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96889560
Alt. Phone Number	-
Email Address	AOCK99@YAHOO.COM.SG
Address	BLK 233 BISHAN ST 22 #04-132
Address complement	-
Postcode	570233
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	5
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	LEE YING LIN
Gender	Female

PASSENGER 2

Name	ONG KAI XUAN
Gender	Male

PASSENGER 3

Name	ONG ZHI XUAN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
---	-----

Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Manufacturer	SMY5384Z
Vehicle Model	Mercedes
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Private car
NRIC No	JEREMY WONG CHUN KIT
Contact Number	SXXXX166J
Address	(Phone) +65-93803391
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHB9779Y
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	-
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	-
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-

Vehicle Category	NA / Unknown
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1


Name of injured person	-
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	-
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report promptly the details of the accident to speed up the claims process.
2. This Form must be completed by the Party's holder, or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to void the policy totally.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation**
6. This report will be forwarded by the insurers to the C.A. Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the completion of this report, the insured, you, hereby consent to the archiving of this report at the centre and to copies of the report being made available thereafter.
8. **Consent under the Personal Data Protection Act (PDPA)**
 I understand, acknowledge, agree and consent that:
 a) My insurer, my lawyer/s and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data (personal information) set out in this [form] and any other personal information provided by me or possessed by my insurer/ lawyer/s (the **Personal Information**), and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident, all insurers who have insured vehicles involved in this accident, all lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency and/or Nominated Police, for the purposes of:
 (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
 (ii) investigating the accident and/or my claim;
 (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 (iv) administering my claims, including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of relevant postal packages; and/or
 (v) complying with applicable law in data handling, processing, handling and/or dealing with my claims.
 collectively the **Purposes**.
 b) All insurers, who have insured vehicles involved in this accident and the insurers, lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
 c) My Personal Information may also be disclosed by any of the insurers and/or GIA to their third party service providers or agents, including the lawyers/law firms, which may be based outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature: *[Signature]* Date & Time: 03/10/22
 Driver's Signature (if driver is not the policyholder): _____ Date & Time: _____
 Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card): _____



Describe Circumstance of the Accident


At around 9pm I was travelling along PIE towards Chaigns direction near Steven Rd east of 90 km/h. Suddenly at around noon away, I saw some vehicles stopped at Lane 1 of the highway and I applied brake to slow down.

I managed to stop in front of the stalled vehicles (actually there was another accident). I waited for about 5 sec before trying to ~~fit~~ filter to Lane 2 so that I can overtake the stalled vehicle. However before I can filter out, I heard a loud ~~sound~~ behind my vehicle and followed by another loud sound and felt my vehicle surged forward.

I quickly pressed the hazard light & ad alighted to check what happened. I saw a Merc A180, SM/538VZ hit onto the rear of my vehicle.

Declaration

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel / Name as in NRIC / ID card