

CS/TM/22.009781/703

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CCPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	03/10/2022
Vehicle Reg. No.:	SHC7719D	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Vehicle Reg. Date:	30/10/2019
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	G4LEKU377533	Chassis No:	KMHC851CVLU180963
Odometer:	421557 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,820.04
Miscellaneous Items	11.00
Labour	1,220.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,051.04
+ GST 7.00% (S\$)	213.57
Nett Amount (S\$)	3,264.61

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 04 Oct 2022)**Parts:** 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC7719D/04/10/2022 10:27**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	un *459.40 FL ✓
2	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	de *451.25 FL ✓
3	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	cr *394.80 FL ✓
4	1		*REAR BUMPER REINFORCEMENT STAY LH	20.00	0.00	bt *138.10 FL ✓
5	1		*REAR BUMPER LOWER MOULDING	20.00	0.00	mx *155.00 FL ✓
6	10		*REAR BUMPER CLIPS	20.00	0.00	un *22.00 FL ✓
7	1		*REAR BUMPER TOW COVER	20.00	0.00	de *98.80 FL ✓
8	1		*REAR BUMPER BRACKET LH	20.00	0.00	de *55.80 FL 33-10 ✓
9	1		*REAR BUMPER REFLECTOR LH	20.00	0.00	un x *41.25 FL ✓
10	1		*REAR BUMPER NUMBER LAMP LH	20.00	0.00	un x *82.30 FL ✓
11	1		*REAR BUMPER FOG LAMP	20.00	0.00	un x *20.10 FL ✓
12	1		*REAR BUMPER MAT	0	0.00	un *50.00 FS ✓
13	1		*REAR NUMBER PLATE W/HOLDER	0	0.00	un *55.00 FS ✓
14	1		*REAR REVERSE SENSOR	0	0.00	un *180.00 FS ✓
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (\$\$)		2,203.80
				- List Item Discount on L Items (\$\$)		383.76
				Total Parts (\$\$)		1,820.04

ComfortDelGro Engineering Pte Ltd/SHC7719D/04/10/2022 10:27. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

20% 1705.45
1364.36
SW 230

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$)

11.00

11

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

350

800.00

2 SPRAY PAINTING

New

250

300.00

3 REMOVE/REFIX REVERSE SENSOR

New

30

60.00

4 TUFF COATING

New

un x

60.00

Gross Labour Cost (\$)

630

1,220.00

ComfortDelGro Engineering Pte Ltd/SHC7719D/04/10/2022 10:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 9749549
WP 4/10/22 @ 3pm
2 days
L/S Resurvey after repair
Tanpin @ 11h auto com

1364-36
SN 230
11
630
2235-36 #
2 days #

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date/Time: 04.10.2022 09:42 Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4944783

JC NO: 805532121


CUSTOMER
IR/MS CITYCAB PTE LTD
CUSTOMER NO. 7010070
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
EL. (R) 65551188 (O)
(P)
DISCOUNT CARD NO.

REGN NO.: SHC7719D	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 03.10.2022 15:30
YR OF MANU. 30.10.2019	TARGET DATE
CHASSIS CODE KMHC851CVLU180963	COMPLETION DATE/TIME:

Accident Date: 03.10.2022
NATURE: 3P 03.10.2022

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledge Slip

Exit Pass

Name:
No.:
Vehicle No.: **SHC7719D** **CHIANG**

Vehicle No.: **SHC7719D**

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard