

 Service Request Details

Claim	S2M04BR5
Reference	CS3/ASM22009792/Gwy3m4 
Loss Date	23 September 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	27 Sep 2022 1:43:08 PM
Request Date	4 October 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	SJR7133R
Vehicle	
Registration #	
Make	TPVD Toyota
Model	COROLLA

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

KHOR Saw Theng

sawtheng.khor@axa.com.sg

Additional Instructions

Messages1InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED			
NAME		TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 RE: S2M04BR5_[TP REF:SJR7133R] _Accident Involving SHD3116P & SJR7133R_along_Oxley Rd on 23/09/2022 08.eml.10_PersonalAutoLine		Other	Other	Lua SiewHui	

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2206277.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	10 October 2022
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	10 October 2022
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	10 October 2022
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	10 October 2022
 SJR 7133R - Preliminary Advise.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 October 2022
 SHD3116P INSD GIA.pdf.pdf	Reports & Statement	GIA Report	KALE Nagesh	30 September 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 SJ0G229N000Q-SHD3116P.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	27 September 2022