

References

ASSIGNMENT

Veh No: 1Q 18174 Yr Regn: 2017 / Dec.

Type: M.Car / M.Cycle / Bus / Van Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Isuzu NPR85 C.C. 2999

Colour white A/C: Insured / Std / NI / NA

Sp. Reading 126579 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JAANNR85HK7100488

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 7.00 R16.

R: 7.00 R16.

	
N/S	O/S

	
N/S	O/S

Front Rear

Front Rear

R/Bal.  mm R/Bal.  mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. 03/10/22

*Survey held at Ryder 7/6

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

TP China

mv :

PV:

Nett:

☐: Prel. Report

Final Report

Add Fee: : Site Insp (\$

Resurvey No. of Trip:

Transportation:

Photos

Others

Report Formed :

5 FEBRUARY 2005 LIU ET AL.