



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22009801/Awy3m4 Date: 20/12/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBC 9753L	Veh. Inspected	YQ 193R
Policy No.		Coverage (\$)	0.00
Claim No.	D22003086MFCV	Excess (\$)	0.00
Assign From	HARMINDER KAUR	Assign Date	04/10/2022
2. Vehicle Particulars & Condition			
Make & Model	HINO XZU710R	c.c	4009
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JHHUCV3H40K028764	Colour	GREEN
Odometer	165182 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	7.00 R16	ARIVO	6 mm
L/H Front Tyre	7.00 R16	ARIVO	6 mm
R/H Rear Tyre	7.00 R16	SWALLOW	6 mm
L/H Rear Tyre	7.00 R16	SWALLOW	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/10/2022	Inspection Date	04/10/2022
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	