



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22009807/Acy3q2 Date: 13/02/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJW 8073Y	Veh. Inspected	SMN 3424M
Policy No.	P10296477R02	Coverage (\$)	0.00
Claim No.	C10017847/CH	Excess (\$)	0.00
Assign From	SALIZAWATI HAIZAR	Assign Date	04/10/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA CITY	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MRHGM6660LT000069	Colour	BLUE
Odometer	106461 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/60 R15	DUNLOP	6 mm
L/H Front Tyre	195/60 R15	DUNLOP	6 mm
R/H Rear Tyre	195/60 R15	DUNLOP	6 mm
L/H Rear Tyre	195/60 R15	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/10/2022	Inspection Date	05/10/2022
Survey held at	J-MART MOTOR PTE LTD BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C SINGAPORE 539186		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	