

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD Ref: NS/INC2200					Гwcm4	
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	14-11-2022		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	FBJ 6644B	Veh. Ir	nspected	SHA 1683Y	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1196338-001	Exces	· · ·	0.00	
	Assign From		Assign	n Date	03/10/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	c.c		1798	
	Engine No.	HIDDEN	Year o	f Reg.	2017	
	Chassis No.	JTDKB3FUX03558774	Coloui	r	BLUE	
	Odometer	945883	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	LAKE	6 mm	
	L/H Front Tyre	195/65 R15	WEST	LAKE	6 mm	
	R/H Rear Tyre	195/65 R15	WEST	LAKE	6 mm	
	L/H Rear Tyre	195/65 R15	WEST	LAKE	6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	29/09/2022	Inspec	tion Date	03/10/2022	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	D. Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days				