ASS. REC BY: Taufik REF: INC.

ASSIGNMENT

From: ______ Date: ______

Estimated Cost: ______

OD / TP / NS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: ______

at Workshop m/s ______

of ______

Insured: ______

Policy No. ______

Claims No. ______

Sum Insured: ______ Excess: ______

(Client's Record)

Make of Veh: ______

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: ______

IDAC Accident Rport: ______ Consistent? : Yes or No

GIA / PR Seen: ______ Consistent? : Yes or No

Est. Repairs: ______ days Res.: Yes or No

Lum Sum: ______ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: ______ Person Contacted: Mr Loke

Veh No: SHA1683Y Yr Regn: 2017 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or ______

Make: Toyota Prius C.C 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp.Reading: 945883 T/Radio: Insured / Std / NI / NA

Eng/No: ______

C/No: JTDKB3FUX03558774.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or ______

Brake: Inorder / Jammed / Leaked / Burnt or ______

Modi : Nil / S/Rim / STD A/Rim or ______

Tyre Size: F: 195/65R15

R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Westlake.

Front			Rear		
R/Bal.	6	mm	R/Bal.	6	mm
L/Bal.	6	mm	L/Bal.	6	mm
D.O.A.			D.O.I.	3/10/22	

Survey held at: Comfort Loyang

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ______ ☐ : Final Report

Date/Time, File Return to?

2) ______

Report Format : ______

Lump Sum / I.B.R ($ ______)

Days Of Repair: ______

Resurvey No. of Trip: ______

Add Fee: ☐ : Site Insp ($ ______)

☐ : Interview ($ ______)

☐ : Tech. Invs ($ ______)

☐ : Weekend ($ ______)

Survey Fee:	
Transportation:	
__S + RS__SI	
Photos	
Others	
TOTAL	

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA1683Y
Make : Toyota
Model : Prius

Date: 03.10.2022
Insurance: INCOME
MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	MIRROR ASSY , OUTER REAR VIEW RH			$ 1,728.70
1	COVER, OUTER MIRROR RG			$ 141.90
	SUB TOTAL			$ 1,870.60
	LESS 25%			$ 467.65
	DISCOUNTED TOTAL			**$ 1,402.95**
	Labour Charge			
	PANEL BEATING			$ 100.00
	SPRAY PAINTING CHARGE			$ 100.00
	CHECK ALL LIGHTING			$ 30.00
	TOTAL LABOUR			**$ 230.00**
	ESTIMATE TOTAL			**$ 1,632.95**

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tang Mi 97495799
w/p 3/10/22 @ 430pm
L/S Resurvey after repair
0/day
tangmi@...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755
Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717

Date/Time: 03.10.2022 10:32 Page : 1

eam: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4944590 JC No: 3005531963

STOMER	REGN NO.: SHA1683Y / MILEAGE
I/MS COMFORT TRANSPORTATION PTE LTD	MAKE : TOYOTA / FUEL E.....1/2.....F
STOMER NO. 7010045	
DRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717	MODEL PRIUS HYBRID(G4) / DATE/TIME IN 03.10.2022 09:50
.. (R) 65508755 (O)	YR OF MANU. 15.06.2017 / TARGET DATE
(P)	
COUNT CARD NO.	CHASSIS CODE JTDKB3FUX03558774 / COMPLETION DATE/TIME:

JOB DESCRIPTION

ccident Date: 29.09.2022
ATURE: 3P 29.09.2022

/NO LABOR CODE DESCRIPTION



ECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wledgement Slip

:
):
e No.: SHA1683Y YY

of Service Advisor

Signature/Date

returned to Service Reception upon collection

Exit Pass

Vehicle No.: SHA1683Y

Name of Service Advisor

Date

To be kept by Security Guard