COMFORTDELGRO ENGINEERING

Our J	lob Re	f No 👔	305531878					
Date 06.10.22					ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156			
FINA	LIZAT	ON FORM				Fax: 6546	18156	
То	:		LKK		F	ax:		
Attn : MrTAUFIKH								
Vehicle Reg No. SHA4777R					Date of Accid	ent:	01.10.22	
The s	urvey	and estimates of	the repairs of the above	-mentioned vel	nicle are as f	ollows:-		
1.	The repair job shall bill to:			INCOME	3		SLB7344J	
2.	The f	inalized amount s	shall be:					
	(a)	Spare Parts after						
	(b) Labour Charges							
	. ,	Total for Part-By-Part Repair Cost						
	(c.)	Lumpsum Repa Total for Lumps Final Lumpsun	um repair cost after Les	s: 20	0%		\$3,350.00	
3. 4.	Estimated normal period for repairs: working days. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days							
5.	finalized amount							
	Signa		- XV		Signature:		taufikh	
	Name : JUMANI			Name : <u>TAUFIKH</u> Data : 11/11/22				
	Tel Fax	62148315 65468150			Date	11/11/2		
For O	fficial	Use Only						
	ļ	tem	Amount	Documer Attacher Yes or N	d (Signatu		Remarks	
Rental Rate P/Day				YES				
2. Loss of Income Paid			STATE:	NO				
3. Survey Fees								
LTA Search Fee 5. Medical Fees (on behalf of driver, if applicable) 6. Overrun			\$7.49 / \$2.00	YES				
Remar	ks: 							