

REPAIR ESTIMATE

Vehicle No. : SHC2547R

Date: 03/10/2022

Make : HYUNDAI

Insurance: INCOME

Model : IONIQ(G2)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			\$ 481.10 <i>de -</i>
10	FRT BUMPER CLIPS			\$ 22.00 <i>de -</i>
1	FRT BUMPER SIDE BRACKER RH			\$ 28.00 <i>de -</i>
1	FRT BUMPER MOULDING CENTRE UPPER			\$ 368.50 <i>dra -</i>
1	HEADLAMP RH			\$ 2,110.30 <i>X</i>
1	DAY LIGHT RH			\$ 642.50 <i>ent -</i>
1	FRT BUMPER SIDE MOULDING RH			\$ 93.60 <i>ent -</i>
1	EMBLEM - BLUE DRIVE RH			\$ 26.60 <i>X</i>
SUB TOTAL				\$ 3,772.60
LESS 20%				\$ 754.52
DISCOUNTED TOTAL				\$ 3,018.08
FRT FENDER ADVERTISEMENT STICKER RH				\$ 100.00 <i>X</i>
				\$ 100.00
Labour Charge				
PANEL BEATING				\$ 800.00 <i>350</i>
SPRAY PAINTING CHARGE				\$ 600.00 <i>250</i>
TUFF KOTE				\$ 60.00 <i>X</i>
CHECK ALL LIGHTING				\$ 60.00 <i>30</i>
TOTAL LABOUR				\$ 1,520.00
ESTIMATE TOTAL				\$ 4,638.08

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495745
 WP 3/10/22 @ 4pm
 LK Rising after repair
 Tanpin & Kuantan. 10-
 2 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 03.10.2022 12:38

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4944635

JC NO: 805532064


CUSTOMER
V/MS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
L. (R) 65508755 (O)
(P)
SCOUNT CARD NO.

REGN NO.: SHC2547R	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 03.10.2022 12:10
YR OF MANU. 24.01.2019	TARGET DATE
CHASSIS CODE KMHC851CVKU133901	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 30.09.2022
NATURE: 3P 30.09.2022

/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC2547R YY

Vehicle No.: SHC2547R

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard