

ASS. REC. BY:

REF: C121

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1.51 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1. GIA not ready

Veh No:

SMS 5846P

Yr Regn:

031 20

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai

Avent

c.c

1591

Colour

M. White

A/C:

Insured / Std / NI / NA

Sp. Reading

186952

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KM1H0841CMLU 034261

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Intertrac

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

1/10/22

D.O.I.

4/10/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt & N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fines

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Date: 03/10/2022
Vehicle No: SMS5846P
Model: HYUNDAI AVANTE 1.6 GLS
Chassis: KMHD841CMLU034261 - 2019
Reg. Year: 2020

Not Authorised
Repairing B4 paint
4 days

Third Party Insurer: CHINA TAIPING
Third Party Veh No: GX6158E
Date of Accident: 01/10/2022
Estimator: KIT
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR RH	1		<i>By</i> \$1,993.70
2	FRONT DOOR SIDE MIRROR WITH COVER RH	1		<i>Car</i> \$281.50
3	FRONT DOOR WEATHERSTRIP RH	1		<i>Pen</i> \$145.80
4	FRONT BUMPER	1		<i>K</i> \$987.60
5	FRONT FENDER RH	1		REPAIR
6	FRONT SPORT RIM RH	1		REPAIR
SUB TOTAL				\$3,408.60
LESS 20%				\$681.72
PARTS TOTAL				\$2,726.88

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR BLACK TAPE STICKER RH	1		<i>Ma</i> \$50.00
S/N TOTAL				\$50.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS. \$500.00 *300*

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS. \$700.00 *460*

TO TUFF KOTE & UNDERSEAL MATERIALS. \$100.00 *30*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$80.00 *20*

LABOUR TOTAL \$1,380.00

KIT TOTAL \$4,156.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Head office

5 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 564500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	177M

Vehicle Details

Vehicle No.:	SMS5846P
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Oct 2022
Vehicle Make:	HYUNDAI
Vehicle Model:	AD AVANTE 1.6 GLS (A)
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	G4FGKU022073
Chassis No.:	KMHD841CMLU034261
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$12,836.00
Original Registration Date:	03 Mar 2020
First Registration Date:	03 Mar 2020
Transfer Count:	0
Actual ARF Paid:	\$12,836.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Mar 2030
PARF Rebate Amount:	\$9,627.00

Intended COE Rebate Details

COE Expiry Date:	02 Mar 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$30,010.00
COE Rebate Amount:	\$22,246.00
Total Rebate Amount:	\$31,873.00

The information contained herein is correct as at 03 Oct 2022

OK