



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



### AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD

Ref: NS/INC22009892/Tqcq2

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

Date: 15-11-2022

Code: INC4

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJP 2436K	Veh. Inspected	SHA 6445K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1196747 -001	Excess (\$)	0.00
Assign From		Assign Date	06/10/2022

#### 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVLU188879	Colour	BLUE
Odometer	335513	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.
---

#### 5. General Information

Accident Date	06/10/2022	Inspection Date	06/10/2022
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------