

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT					
INCOME INSURANCE LTD			Ref:	NS/INC22009893/Gvcm4	
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	01-11-2022 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SNE 1272H	Veh. Ir	spected	SHD 3179H
	Policy No.		Covera	age (\$)	0.00
	Claim No.	MT/1191398-002	Exces	s (\$)	0.00
	Assign From		Assign	n Date	05/10/2022
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI I40 1.7	c.c		1685
	Engine No.	HIDDEN	Year o	f Reg.	2016
	Chassis No.	KMHLB41UMGU091848	Coloui	•	BLUE
	Odometer	637007	Steerii	ng	IN ORDER
	Brakes	IN ORDER	Modifi	cation	NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/60 R16	WEST	_AKE	6 mm
	L/H Front Tyre	205/60 R16	WEST	_AKE	6 mm
	R/H Rear Tyre	205/60 R16	WEST	_AKE	6 mm
	L/H Rear Tyre	205/60 R16	WEST	_AKE	6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	04/10/2022	Inspec	tion Date	05/10/2022
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969				
5a.	. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				