



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD  
16 RAFFLES QUAY  
#42-01 HONG LEONG BUILDING  
SINGAPORE 048581

Ref: CS/FCI22009900/Any3e2

Date: 10/04/2023

Code: FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |               |                       |            |
|---------------------|---------------|-----------------------|------------|
| <b>Insured Veh.</b> | SG 6299D      | <b>Veh. Inspected</b> | SKU 8751Y  |
| <b>Policy No.</b>   |               | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | D22003121MFBP | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | AINI BINTE    | <b>Assign Date</b>    | 06/10/2022 |

### 2. Vehicle Particulars & Condition

|                         |                  |                     |            |
|-------------------------|------------------|---------------------|------------|
| <b>Make &amp; Model</b> | HONDA CIVIC      | <b>c.c</b>          | 1595       |
| <b>Engine No.</b>       | HIDDEN           | <b>Year of Reg.</b> | 2011       |
| <b>Chassis No.</b>      | JHMF4620AS200181 | <b>Colour</b>       | GREY       |
| <b>Odometer</b>         | 164482 KM        | <b>Steering</b>     | IN ORDER   |
| <b>Brakes</b>           | IN ORDER         | <b>Modification</b> | SPORTS RIM |
| <b>General</b>          | GOOD             |                     |            |

### 3. Conditions of Tyres

|                       | Size       | Make   | Balance |
|-----------------------|------------|--------|---------|
| <b>R/H Front Tyre</b> | 205/55 R16 | DUNLOP | 6 mm    |
| <b>L/H Front Tyre</b> | 205/55 R16 | DUNLOP | 6 mm    |
| <b>R/H Rear Tyre</b>  | 205/55 R16 | DUNLOP | 6 mm    |
| <b>L/H Rear Tyre</b>  | 205/55 R16 | DUNLOP | 6 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

|                       |   |                        |            |
|-----------------------|---|------------------------|------------|
| <b>Accident Date</b>  | 05/10/2022  | <b>Inspection Date</b> | 07/10/2022 |
| <b>Survey held at</b> | N-51 AUTOMOTIVE PL<br>2 KAKI BUKIT AVE 2<br>#01-17 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921 |                        |            |

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**