

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SKU8751Y Yr Regn: 2011, Jan.  
 Type: (M.Car) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Honda Civic c.c 1595  
 Colour: Grey A/C: Insured / Std / NI / NA  
 Sp. Reading: 164482 / T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JHMF04620AS200181  
 Gen. Cond: (Good) Fair / Poor / Burnt  
 Steering: (In order) Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: (In order) Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modif: Nil (S/Rim) / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 205/55R16  
 R: 205/55R16

BS: (DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 07/0/22.  
 Survey held at NSI.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear o/s.  
 The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 34k  
 IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 6 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>TP 1st Cap.</u>
	<u>COE Expiry: 31/12/25.</u>
	<u>Adrian confirmed lump sum \$3400 and 6 days</u>
	<u>MV: (red, 3487.44, 50%)</u>
	<u>PV: mv \$34k-lta \$12063=mv \$21937</u>
	<u>Nett:</u>

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) 10/04/23  
 Date/Time, File Return to?

Days Of Repair: 6  
 Resurvey No. of Trip: 2

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Inve (\$)

Survey Fee:	<u>145</u>
Transportation:	<u>50</u>
S + RS. \$1	<u>50+50</u>
Photos	<u>59</u>
Others	
	<u>354</u>

Report Format: tp  
 \_\_\_\_\_ 3400