

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |   |                |       |                        |  |
|---|--|---|----------------|-------|------------------------|--|
|   | HSBC LIFE (SING  | APORE) PTE LTD  |                | Ref:  | CC4/ASM22009903/Apa3q2 |  |
|   | 10 MARINA BOULI<br>#48-01 MARINA BA<br>2SINGAPORE 018  | AY FINANCIAL CENTRE TOWER   |                | Date: | 14/03/2023             |  |
|   | ATTN:CYNTHIA   |   |                | Code: | HSB                    |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM  |   |                |       |                        |  |
|   | Insured Veh.   | SJF 4553U   | Veh. Inspected |       | SLE 9318G              |  |
|   | Policy No.   | GA518924  | Coverage (\$)  |       | 0.00                   |  |
|   | Claim No.  | S2M04CDH  | Excess (\$)    |       | 0.00                   |  |
|   | Assign From  |   | Assign Date    |       | 06/10/2022             |  |
| 2. Vehicle Particulars & Condition                                |  |   |                |       |                        |  |
|   | Make & Model   | HONDA VEZEL HYBRID  | c.c            |       | 1496                   |  |
|   | Engine No.   | HIDDEN  | Year of Reg.   |       | 2016                   |  |
|   | Chassis No.  | RU31126100  | Colour         |       | BRONZE                 |  |
|   | Odometer   | 94335 KM  | Steering       |       | IN ORDER               |  |
|   | Brakes   | IN ORDER  | Modification   |       | SPORTS RIM             |  |
|   | General  | GOOD  |                |       |                        |  |
| 3. Conditions of Tyres  |  |   |                |       |                        |  |
|   |  | Size  | Make           |       | Balance                |  |
|   | R/H Front Tyre   | 215/55 R17  | SETULA         |       | 6 mm                   |  |
|   | L/H Front Tyre   | 215/55 R17  | SETULA         |       | 6 mm                   |  |
|   | R/H Rear Tyre  | 215/55 R17  | SETULA         |       | 6 mm                   |  |
|   | L/H Rear Tyre  | 215/55 R17  | SETULA         |       | 6 mm                   |  |
| 4.  | . Description of Damages   |   |                |       |                        |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.   |   |                |       |                        |  |
|   | DAMAGES SEE DETAILS.   |   |                |       |                        |  |
| 5.  | General Information  |   |                |       |                        |  |
|   | Accident Date  | 05/10/2022  | Inspection Dat | е     | 07/10/2022             |  |
|   | Survey held at   | MG SOLUTION PTE LTD   |                |       |                        |  |
|   |  | 23 KAKI BUKIT AVE 4<br>(SOUTH WING) #02-03B<br>VICOM INSPECTION CENTRE,<br>SINGAPORE 415933 |                |       |                        |  |
| 5a.   |  |   |                |       |                        |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                |       |                        |  |
| 5b.   | Estimate Days of Repair  |   |                |       |                        |  |
|   | ESTIMATED NOR  | ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days  |                |       |                        |  |