



Your Ref: S0M02VCC

Date: 01st Nov 2022

Our Ref: CS3/ASM20011055/Evy3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Oh Vale

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBD 1158C
INSURED VEHICLE: SBJ 7E
ACCIDENT DATE: 10/10/2020**

We thank you for your instruction on 06/10/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBD 1158C from M/s Impact Analysis Consultant.
- b) Singapore Accident Statement of Vehicles GBD 1158C and SBJ 7E.
- c) Final Repair Bill of GBD 1158C from M/s Garage 13 Pte Ltd.
- d) Colour damaged vehicle photographs of GBD 1158C.

Pre-Repair Inspection Date: 13/10/2020 at M/s Garage 13 Pte Ltd, 8 Kaki Bukit Ave 4 #03-46 Premier, Singapore 415875.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : GBD 1158C
Make & Model : Nissan Cabstar 3.0 5M/T ABS 2DR 2WD Euro 5
Year of Registration : 2014
Chassis Number : JN1SC2F24Z0855868
Engine Capacity : 2953 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.