



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22009910/Kny3q2 Date: 28/10/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMV 7331D	Veh. Inspected	SMK 992A
Policy No.	PP10628420R00	Coverage (\$)	0.00
Claim No.	C10017913/JL	Excess (\$)	0.00
Assign From	SALIZAWATI HAIZAR	Assign Date	07/10/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GK82001484	Colour	METALLIC PEARL WHITE
Odometer	132778 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/55 R15	YOKOHAMA	8 mm
L/H Front Tyre	195/55 R15	YOKOHAMA	8 mm
R/H Rear Tyre	195/55 R15	YOKOHAMA	8 mm
L/H Rear Tyre	195/55 R15	YOKOHAMA	8 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	05/10/2022	Inspection Date	07/10/2022
Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days