301999553654



60222461

12 Eu Tong Son Street
The Central (SOHO 2) #05-172
Singapore 059819
UEN No. 201310922K
Tel: [65] 6438 5500
Fax: [65] 6438 0111
www.cutherinelimilc.com
Email: Info@cathorinelimilc.com
CATHERINE LIM LLC is a law
corporation with limited hability

CATHERINE LIM LLC

- 林 ADVOCATES & SOLICITORS
- 率 NOTARY PUBLIC -公证官
- 珍 COMMISSIONER FOR OATHS- 宣誓音
- IN CATHERINE CL.UM
- 知 DIRECTOR LLB (HONS) SINGAPORE-法律系-排解 M.B.A. (BUSINESS LAW)-商业系 硕士

Our Ref: CL/220821/T/APEX.sg

11 August 2022



M/s AXA Insurance Singapore Pte Ltd 9 North Bouna Vista Drive #18-01/06 The Metropolis Tower 1 Singapore 138588 Atta: Motor Claims Dept

Sekar Samson Bik 305 Jurong East Street 32 #03-144 Singapore 600305

Dear Sir

WITHOUT PREJUDICE (to any personal injury claim) By Hand



CERTIFICATE OF POSTING

(Please be informed that all supporting documents have been forwarded to your insurer.)

ACCIDENT INVOLVING SMF 4959Y / SLU 786M ON 14.07.2022 ALONG BUKIT TIMAH ROAD TOWARDS WOODLANDS ROAD (BEFORE FOURTH AVE)

We act for ASIA EXPRESS CAR RENTAL PTE LTD, the owner of motor vehicle No. SMF 4959Y, which was involved in the above accident.

Our client has suffered loss and damage as a result of your insured's negligence in the driving of motor vehicle No. SLU 786M.

We quantify our client's claim as follows:-

1. 2. 3. 4. 5. 6.	Cost of repairs Loss of use (12 days x \$150) Survey fee GIA/LTA searches Incidentals, transport & photocopying etc Cost contribution		2,450.00 1,800.00 926.00 39.00 53.50 963.00
		\$10	6,231.50

We enclose herewith photocopies of our client's accident report, LTA/GIA searches, repair bill, survey fee, survey report and colour photographs of our client's damaged vehicle for your immediate attention.

Please let us know within the next 14 days from the receipt of this letter, whether you are prepared to admit liability and revert with a settlement proposal, failing which our clients shall have no alternative but to commence legal proceedings against your insured.

Yours faithfully

Encs cc; clients SJBC227M0063 / JOO HAK KEE AUTO PTE LTD ENTRY DATE & TIME: 22/07/2022 17:07 (SGT) SUBMITTED BY Poli Shi Min VERSION: 1 (22/07/2022 17:02 (5GT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process.

This Form must be complained by the Policyholder and/or the Authorised Drivet
 Information provided must be as truthful and accurate as possible. Any with misrepresentation or witholding of material facts may allow insurance companies to repud are

The issue and ecceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any felse reporting may be referred to the Police for investigation.

5. Any felse reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Corons established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you horoby consent to the archiving of this report at the centre sent to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Reported by Date of Accident Exact Location of Accident

Additional Location Information

Country/State of Loss

22/07/2022 17:02 (SGT)

Driver

14/07/2022 01:05 (SGT) Bukit Timah, Singapore

TOWARDS WOODLANDS ROAD (BEFORE FOURTH AVE)

Singapore

DETAILS OF DWN VEHICLE

Vehicle Registration Number

SMF4959Y

INSURED/POLICYHOLDER

is company?

Name Of Registered Owner

Company Reg No **Email Address**

Mobile Phone No

Alternative Phone No

ASIA EXPRESS CAR RENTAL PTE LTD

2XXXXX882D

PEIJIE@EXPRESSCAR.COM.SG

(Phone) +65-91998131

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Transmission

CC

Toyota

Prius

HYBRID 1.8S CVT

Private hire

No - Claiming third party

Private hire

Auto

1797

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

NTUC Income Insurance Co-operative Ltd

5126469337

DRIVER

Name of Driver NRIC No

Date Of Birth Occupation

ANG YIAK CHIANG SXXXX106J 03/04/1964 Outdoor



Date Of Driving Pass Driving experience

Gender Mobile Number

Alt. Phone Number Email Address

Address

Address complement

Postcode

is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

11/12/1984

37 YEARS AND 7 MONTHS

Male

(Phone) +65-94595566

PELJIE@EXPRESSCAR.COM:SG BLK 50, SIMS DRIVE #24-142

380050

No

Hirer

No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Collision - Head to Rear

Clear Dry

No

Yes.

Yes

Yes

2

No

2

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged? Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's name

Translator's ID

Translator's phone number

Translator's email.

Original language used in the statement

PASSENGER 1

Name Gender

UNKNOWN Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? Police Station Name Police Station Phone No. Alt. Police Station Phone No. Police Station Address

Was notice of intended Prosecution given?

If yes, against whom?

Yes

Traffic Police

(Phone) +65-65470000 (Fax) +65-65474900

10 Ubi Avenue 3 Singapore 408865

No

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category

Name of Driver NRIC No Contact Number

Address

Address complement Postcode

Insurance Company Name Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

SLU786M Porsche Cayenne

Black Private car SEKAR SAMSON

SXXXX634B (Phone) +65-91770732

1

SERIOUSLY DAMAGED

RIGHT FRONT WHEEL, BUMPER & MUDGUARD BADLY

DAMAGED

- 4

INJURED PERSONS DETAILS

INJURED 1

Name of injured person Gender

Phone No Address

Address Complement

Post Code

Approximate Age Years Old

Injuries Sustained

Injured person in which vehicle?

Were seat balts wom?

Was this injured conveyed to hospital by ambulance?

ANG YIAK CHIANG

Male

(Phone) +65-94595566 BLK 50, SIMS DRIVE #24-142

380050

58

7 DAYS MC SMF4959Y

No

Yes

SKETCH PLAN

IMPORTANT NOTICE

- 1. Rease report <u>correctly</u> the details of the occident to speed up the claims process.
- 2. This Formatust be completed by the Policyholder and/or the Authorised Driver
- 3. Wormston provided must be as truthful and accurate as possible. Any wiful managementation or will including of material facts may allow incurance companies to repodiate policy liability
- 4. The issue and acceptance of this Formby insurance companies is not an admission of policy liability on the part of the insurance
- 5 Any false reporting may be referred to the Police for love a finaling
- 5. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association
- of Singapore (GA) for archiving and that copies of this report will for a fee be made available upon application by interested parties. 7. By the bidgement of this report to the insurers, you haraby consent to the archiving of the report at the centre and to copies of the 8. Consent under the Personal Data Protection Act (PDPA)

lunderstand, actnowledge, agree and consent that

(a) My incurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, discussed another process my personal data personal information set out in this (form) and any other paraginal information provided by the or consequed by my mauter (collectively the "Personal Information") and docking and transfer such Personal Information to all insurence) who have around vehicle(s) involved in this acceptal (all instructs) who have assured vehicle(s) involved in this accepts and the collectively referred to as the "Insurers"), the housers' the yellotine form the Moretiny Authority of Singapore and any relavant government agency/assnorty (such as the solice), for the purpose(s) of

(ii) processing, handing end or dealing with my claims including the sectionest of the claims and any necessary investigations rolling to

(ii) investigating the accorded wedler my claims,

(46) carrying out analyst degling with my instructions of responding to any experies by me:

(w) advantating my diams (including the making of correspondence, statements, visitions, reports or notices to me, which could myster decidence of cortain personal data about me to bring about delivery of the sume as well about the enternal cover of anicological mast


(v) complying with applicable law in administrating processing, building arriver dealing with my cleans.

(b) of respect(s) who have insured vehicle(s) evolved in the accident and the insurers' lawyors from mayber permitted to solver, decides and/or process my Personal Information for one of orders of the above Purposes; and



mi.

Dogo 4 of 12



Declaration

Whe decises the foregoing particulars are true in every respect.

OD

Policyholder's Signature / Otto &

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre Personnel

















Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

1003 Report No. T/20220714/7005

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/07/2022 04:25			Vide Report No.: E/20220714/0008	Station Diary No.		
Informa	nt's Partic	ulars		THE PARTY OF THE P		
	lame of Informant: NG YIAK CHIANG		Address: 50 SIMS DRIVE #24-142 SINGAPORE 380050			
	/ ID No.: 0 / \$16651	063	Contact No.: Home/Office:	Mobile: 94595565		
National SINGAP	ily: ORE CITIZ	EN	Email: YCANG64.AYC@GMAIL.CO	сом		
Sex: Male	Age: 58	Date of Birth: 03/04/1964	Type of Informant: Driver			
Race: Chinese			Language: Institution / School Na English			
Occupation:			Driving Licence Information: Class:	Date of Expiry:		

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 14/07/2022 01:03	Type of Location Straight Road
BUKIT TIMAH	ROAD			
Weather:		Road Surface: Dry		Road Speed Limit 70 Km/h
Clear				
Traffic Flow: One Way		Traffic Control: Traffic Light - Wor	king	Traffic Volume: No Traffic

Vehicle No.	Type	Mako	Model	Color	Conditio	No of
SLU786M	Car	PORSCHE	Cayenne	Black	Seriously Damaged	1.5
SMF4959Y	Car		_			0



Tel No: 85470000

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865

Report No. T/20220714/7005

CONTINUATION OF REPORT

Details of Perso				
Any Pedestrian I		110000000000000000000000000000000000000	-	CONTACA II
No. of Pedestria	ns Injured: NIL	Use of Pe	destrian Cross	sing: NA
Driver	A STATE OF THE STA			POTOTOTO DE
Name	SEKAR SAMSON		ID No.	526576348
Related Vehicle	SLU786M (Car)		Contest No.	91770732
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL	
No. of Days gran	ted Medical Leave NIL	Degree of	Slight	
Driver	ACCOMMON TO A SECOND STREET	2 40 0010		
Name	ANG YIAK CHIANG		ID No.	S1665106J
Related Vehicle	SMF4959Y (Car)		Contact No.	94696666
Hospitel/Clinic	NIL		Class of Driving License & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL	
No. of Days grant	ted Medical Leave NIL	Degree of	NIL	

When my vehicle SMY4959Y reached the traffic light crossing along Bukit Timeh Road towards Woodlands Road before Fourth Ave, around 0105hrs on 14 July 22, the traffic light at the pedestrian crossing is RED, so I stop my vehicle SMY4959Y before the STOP line. The next moment a loud band hits onto my car SMF4959Y and force my car the drift forward.

I was shocked by the band and my passenger sitting behind was also shocked. She claims that she felt

giddy and left in another car. When I came down to check my car, I found out that my vehicle SMF4959Y, left rear wheel and mud guard was seriously damaged and also saw the vehicle SLU786M that hits my vehicle was stopped far in front of my car with the right front wheel, bumper and mud guard were also badly damaged. An ambulance was called and the driver of SLU786M claimed that he was not feeling well and was conveyed by the ambulance to the hospital.



SINGAPORE POLICE FORCE


T-20220714/7005


Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408565 Tel No: 65470000

3 of 3 Report No. 1/20220714/7005

CONTINUATION OF REPORT

B) (DIVIDER ISLAND
(000)
Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Date/Time; 14/07/2022 04:25
Classification Of Case:









Report No. G/20220715/2065

POLICE REPORT (NP299)

Police Station Of Origin Kaki Bukit NPP 526 Bedok North Street 3 #01-448 SINCAPORE 460525 Tel No: 1800-4429999

Date/Time Report Made 15/07/2022 15:38	#P0000-090	port No. 0714/7005		Station Diary No. 16
Name Of Informent ANG YIAK CHIANG	Address APT BL	5.7	DRIVE#24-142.S	INGAPORE 38005
ID Type / ID No. NRIC NO / \$1665106J	Contact Home/C	1/5/27/21	Mobile 94595560	
Nationally SINGAPORE CITIZEN	Email A	ddress	Verific	
Occupation PRIVATE HIRER DRIVER	Sex Male	Agir 58	Date of Birth 03/04/1984	Chinese
Institution/School Name	Language English			
Date/Time Cf Incident. 14/07/2023 01:05	Location Of Incident BUKIT TIMAH ROAD SINGAPORE			
Brief details.	100			

I am lodging this report to add on the MC detail to my traffic accident report T/20220714/7005.

Clinic: Northgest Medical Group

MC No: #455110

Date of MC: 15/07/2022 to 21/07/2022 (7 days)

Diagnosis: Road traffic accident, sprained shoulder, glddiness

TP 10 Incharge: Sitt Norhalfidah Binte Hanali

Signature Of Officer Recording The Report G / SR STAFF SGT MOHAMED NOR BIN MOHAMED ALI JINNAH	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 15/07/2022 15:38
Officer in-Charge Of Case: G / Bedok Police Divisional Investigation Branch / INSP (2) CHIA JI JI Contast No.: 62447200	Classification Of Case:



> Back to OneMotoring

Land Transport Authority

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time :

14 Jul 2022 / 11:23:01

Receipt Date/Time:

14 Jul 2022 / 11:23:01

Tax Invoice/Receipt

Receipt No.: ITNET-00000-220714-001198

Previous Receipt No. :

S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLU786M As at 14 Jul 2022/01:05:00				
Insurance Co: AXA INSURANCE PTE LTD				
1 Insurance Enquiry - SLU786M				
Enquiry Fee 20220714112221029958		7.00	0.49	7,49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7,45
	Paid By			
	426588XXXXXX9400	eNETS (Credit Card	7,45
	Total			7.45
	Cash Change			0:00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



25 Kaki Bukit Road 4 #01-55 S417800

S/no AX-6421

S/no	Description	Amount
1	Parts and labour for repair of Toyota Prius Hybrid SMF4959Y (Lump Sum)	\$12,450
		, A=
	Total:	\$12,450

Vehicle No:

Date: DE V

SMF4959 Y 31 July 2022

Apex Motoring



6 tempines st 73, #01-03, singapore 528825 tel: 6746 2118 fax: 6746 1148

reg no: 53058468m

Claim Reference : Insured Vehicle No. : Thirty Party Veh No. : Officer-In-Charge : -

Our Reference Invoice No. Date

: KAAS/TA/6421/4959/TP/07,22

: 5421 : 31 July 2022

To: Asia Express Car Rental Pte Ltd

c/o 25 Kaki Bukit Road 4

#01-55, Synergy @ Kaki Bukit

Singapore 417800

	INV	OICE	
te/Model : Toyota Prius Hybrid 1.8S CVT Inspection of Vehicle Appraisal Report 8t Colored Photographs SGD 926.00	PARTICULARS		AMOUNT
81 Colored Photographs SGD 926.00	Make/Model : Toyota Prius Hybrid 1.8S CVT Inspection of Vehicle		
✓ Transport charges	81 Colored Photographs		SGD 925.00
✓ Re-inspection			
Others (Specify) Total SGD 926.00	Others (Specify)		

Dollars: Nine Hundred and Twenty-Six Only

(Cheque should be crossed and make psyable to * Kelvin Automotive Appraising Services *)



Kelvin Automotive Appraising Services



6 tampines st 73, #01-03, singapore 528825

tel: 6746 2118 fax: 6746 1148

reg no: 53058468m

Claim Reference : Insured Vehicle No. : Thirty Party Veh No. : Officer-In-Charge : -

Our Reference

: KAAS/TA/6421/4959/TP/07.22

Date

: 3f July 2022

To: Asia Express Car Rental Pte Ltd

c/o 25 Kaki Bukit Road 4

#01-55, Synergy @ Kaki Bukit

Singapore 417800

VEHICLE APPRAISAL REPORT

Name of Workshop

: Apex Moloring

Place of inspection

: 25 Kaki Bukit Road 4 #01-55, Synergy @ Kasi Bukit, Singapore 417800

Date of Assignment

: 14 July 2022

Date of Accident

: 14 July 2022

Date of Inspection

: 14 July 2022

PARTICULARS OF INSPECTED VEHICLE

Registration No.

: SMF 4959Y

Chassis Frame No.

2VV/50-6144369

Make / Model

: Toyota Prius Hybrid 1.8S CVT

Engine No. (Logoard)

2ZR2B37174

Year of Manufacture/Reg

: 2018

Odometer Reading

323,420 KM

Calour

Silver

Class/Type

: Saloon

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition

Good

Paintwork

: Good

Market Value

Scrap Value

8.

CONDITION OF TYRES ON VEHICLE

QNWW.	30	Make/Size	Thread Belance
Front	4	KAPSEN 195 / 65 R15	7 mm
Front	R	KAPSEN 195 / 65 R15	7 mm
Rear	L	KAPSEN 195 / 65 R15	7 mm
Rear	R	KAPSEN 195 / 65 R15	7 mm

^{*}The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended by the exclusive as of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissensation or use of this communication is saidly prohibited. If you have received this survey report in error, please confect as immediately by place so that we can arrange for its return.



6 tempines st 73, #01-03, singapore 528825

tel: 6746 2118 fax: 6746 1148 reg no: 53058468m

Our Reference Vehicle Number : KAAS/TA/6421/4959/TP/07.22

SMF 4959Y

APPRAISEMENT SCHEDULE

S/N	Oty	Descriptions LIST ITEMS:-	Conditions	Repairer's Estimate		Revised Amount	
1	1-pa:	rear bumper	broken	5	1,287.60	\$	1,287.6
2	1 pg	rear bumper ctr lower cover	broken	18	558.30	\$	558,3
3	1 pc	rear bumper reinforcement	backled	1	387.20	\$	387.2
4	1 pc	rear bumper Vh side cover	missing	\$	150,50	\$	150,5
5	1 00	rear bumper I/h side lamp	broken	8	486.60	\$	486.6
6	1.00	rear bumper I/h side retainer	necessary	\$	39,00	5	39.0
7	1 set	rear bumper clips	necessary	\$	35.00	S	35.0
8	1 pc	talgete	buckled	\$	1,129.30	\$	1,129.3
9	1 pc	talgate inner lock	shifted	\$	452.10	æ.	realign
10	1 pc	talgate outer garnish	cracked	S	891,20	5	991.2
11	1 pc	tailgate logo emblem	necessary	\$	48.70	S	48.7
12	1 pc	taigate * prius * emblem	necessary	5	62.10	\$	62.1
13	1 pc	taligate " hybrid " emblem	necessary	.5	58.90	3	58.3
14	1 00	taligate spoler w/ lamp	damaged	5	921,40	4.5	repair
15	1 pc	rear windscreen moulding - small	necessary	S	36.70	5	36.7
16	1 pc	rear windscreen moulding - big	necessary	\$	78.80	\$	76.8
17	1 pg	Vh tallamp	broken	3	673.90	5	673.5
18	1 pc	rear end panel	budited	5	629.80	5	629.8
19	1 po	spore tyre panel	buckled	3	678.70	\$	678.7
20	1 pc	spare tyre panel thisponge tray	deformed	\$	210.00	5	210.0
21	1 pc	Whiside rear under cover	broken	5	158.00	5	158.0
22	1 pe	Vh rear fender	buckled	3	852.20	\$	852.2
23	100	Wh rear fender air vent	broken	\$	102.90	5	102.9
24	100	Vh rear fender spiash shield	broken	3	135.60	5	135.6
25	1 pc	Ifn rear fender inner trim	deformed	\$	314.60	5	314.0
28	1 set	Ifh rear funder inner trim clips	necessary	3	35.00	\$	35.0
27	1 pc	Vh rear door	buckled	1	1,126.70	\$	1,126.7
28	1 pc	Wh rear door lock	jammed	\$	500.10	\$	500.
29	100	Wh rear door outer handle	jammed	15	375.10	\$	375.
30	1 pg	I/h rear door window outer seal	deformed	\$	185.70	\$	185.7
31	100	Ith rear door window regulator	bent	\$	248.60	\$	248,6
32	1 pc	I/h rear door window regulator motor	not working	\$	768.20	\$	768.2
33	1 pc	bit rear door inner trim board	unconfirmed	\$	1,347.60		not affected
34	Lset	I/h rear door inner trim board clips	necessary	\$	35.00	\$	35.0
35	1 pc	Mi side skirt	deformed	1	987.10	\$	987.
36	1 pc	Uh front door	buckled	1	1,226.60		repair
		Less 25%	14.00	\$	17,213.00	S	13,265.3 3,316.3
				\$	17,213.00	5	9,948.9
	_		Sub - Total	\$	17,213.00	\$	9,948.9



ó tampines st 73, #01-03, singaporo 528825 tel: 6746 2118 fax: 6746 1148

reg no: 53058468m

Our Reference Vehicle Number : KAAS/TA/8421/4959/TP/07,22 : SMF 4959Y

APPRAISEMENT SCHEDULE

S/N	Qly	Descriptions	Conditions		Repairer's Estimate	ALC:	Revised Amount
		B/F		5	17,213.0	9 5	9,948.
		LIST ITEMS:-					
37	1 pc	Wh rear wheel rim	distorted	5	800.00	3	fi00.0
38	100	I/h roor tyre @50% depreciation	scratched	3	380.00		190.0
39	1 pc	rear sub frame	buckled	8	1,024.70		1,024,7
40	1 pc	roar stabilizer bar	bent	8	392.10		392.1
41	1 pc	rear stabilizer ber t/h tink	bent:	\$	79.40		79.4
42	1 pc	Whitear shock absorber	tient	15	310.20		310.2
43	1 pc	Whirear upper arm	bent	5	352.80	5	352.6
44	tpc	I/h rear lower arm	bent	5 S	497.30	\$	497.3
45	1 pc	In rear trailing arm	bent	\$	259.70	\$	259.7
46	1 pc	Vh rear knuckie arm	distorted		502.70	\$	802.7
48	1 pc	Ifh rear wheel hub w/ bearing	damaged	5	€22,90		522.9
49	1 pc	fuel tank	damaged	S	789.20		789.20
50	1 pc	fuel tank hose	begamab	\$	172.10		172,10
30	1 pc	fuel tank filler pipe breather	damaged	\$	92.30	\$	92.30
- 1		Less 25%		5	6,375.40	s	6,185.40
- 1		LB38-2076		-		5	1,546.36
				\$	6,375.40	\$	4,639.05
1		SPECIAL NETT ITEMS:-	-1-3	Г			
51	1 roll	roar windscreen soalant	necessary	\$	€0.00	5	40.00
52	1 roll	rear and panel sectant	necessary	\$	60.00	3	40.00
1				8	120.00	\$	80.00
				L			
		1111 - 11 11		F.			
1			Marin Ton	1			
		- W			. 1		
-1-			Sub - Total	\$	23,708.40	\$	14,668.03



6 tampines st 73, #01-03, singapore 528825 tel: 6746 2118 fax: 6746 1148 reg no: 53058468m

Our Reference Vehicle Number : KAAS/TA/6421/4959/TP/07.22 : SMF 4959Y

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate		Revised Amount	
		BIF		\$	17,213.00	\$	9,948.98
		LABOUR & OTHER CHARGES:-					
4)		To panel best and renewal of all necessary demaged body parts		\$	2,600.00		2,400.00
2		To check wiring and rewire		5	60,00	\$	50.00
3		To remove and reinstall tallgate components		\$	80.00	5	60.00
4		To remove and reinstall rear windscreen		\$	\$50.00	\$	120.00
5		To remove and reinstall rear boot upholstery		\$	120.00	S	100.00
6		To remove and reinstall reverse sensor		\$	140,00	s	100.00
7		To remove and reinstall rear quarter glass		\$	100.00	s	80.00
8		To remove and reinstall rear seat custion		\$	240.00	s	200.00
9		To remove and reinstall fuel tank		\$	160.00	5	120.00
10		To perform 4 wheel alignment		\$	120.00	\$	100,00
11		To remove and reinstell rear undercamage		s	240.00	s	200.0
12		To remove and reinstall front door components		\$	80.00	\$	60.0
13		To remove and reinstall rear door components		s	90.06	\$	60.00
14.		To apply anti-rust		s	160.00	5	140.00
15		To putty and apray-point of affected areas		s	2,000.00	\$	1,800.00
101.00				5	6,330.00	\$	5,590.00
		Mark Mark					
	-		Sub - Total	\$	23,543.00	\$	15,538.98



6 tampines st 73, #01-03, singapore 528825

tel: 6746 2118 fax: 6746 1148

reg no: 53058468m

Our Reference Vehicle Number

KAAS/TA/6421/4959/TP/07.22


SMF 4959Y


ASSESSMENT SUMMARY


Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and

the impact was delivered Squarely to the LH Rear

portion of the vehicle.







The general area of damages is at the

LH Rear portion

(Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs

Apex Motoring

s \$ 23,543.00 .

We have adjusted the cost to

15,538.98 and the repairer has agreed to undertake the repairs at a

Contract Lump Sum of \$ 12,450.00 to a acceptable quality and standards.

However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of

12 working days.

81 photographs were taken at the time of static inspection.

This report is strictly done in a Without Projudice Basis.

We are reverting the matter to you a decision.

We enclose herewith our invoice No. we thank you for engaging our services.

6421

for our services rendered and

KELVIN AUTOMOTIVE APPRAISING SERVICES

for

KELVIN TEO

Licensed Automotive Appraiser Nitec in Automotive Technology Cert. Crash Investigation & Reconstruction Dip MS

MSAAA, AM SAE-A

NOTE: This revised estimate was from a visual inspection. Should there be any discrepancy or cossen items not listed in this survey, kindly notify the company within Seven (f) days from the date framed. Otherwise this revised amount shall be treated as valid.

